

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24070388/AUA3Q2**Date:** 14/04/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900243305  
**Claimant Vehicle No :** SJW168K **Insured Vehicle No :** GBG8864K  
 Date of Loss: 24/07/2024 Nature of Claim: TP Claim No: 3937385776SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJW168K**  
 Make & Model: BMW 330I, 2.0 MPST LED HL LED FL (A) Engine No: 10145616B48B20B  
 Reg. Date: 18/06/2019 (Man. Year: 2019) Chassis No: WBA5R12000AK72053  
 Colour: Orange Odometer: 83276 km  
 Engine Capacity: 1998 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R19 Rear Tyre Size: 275/  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|-------------------|-------------------|---------------|
| Parts  | 10,961.00         | 5,925.60          | 5,035.40          | 45.94         |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour   | 7,452.00          | 4,380.00          | 3,072.00          | 41.22         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing   | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>                         | <b>18,413.00</b>  | <b>10,305.60</b>  | <b>8,107.40</b>   | <b>44.03</b>  |
| <b>+ GST 9.00/9.00% (S\$)</b>                    | 1,657.17          | 927.50            | 729.67            | 44.03         |
| <b>Nett Amount (S\$)</b>                         | <b>20,070.17</b>  | <b>11,233.10</b>  | <b>8,837.07</b>   | <b>44.03</b>  |
| <b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b> |                   | 400.00            |                   |               |
| <b>Nett Liability (S\$)</b>                      |                   | <b>11,633.10</b>  |                   |               |

INSPECTION

Date of Assignment: 24/07/2024  
 Date Inspected: 24/07/2024 Inspected At: Premium Automobiles Pte Ltd (HQ)  
 55 UBI ROAD 1  
 Singapore 408699  
 Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING**Manager:** NA MENG YAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No.                          | Qty | Part No. | Particulars                          | Condition     | Repairer's               | Amount                         |
|------------------------------|-----|----------|--------------------------------------|---------------|--------------------------|--------------------------------|
| 1                            | 1   |          | *FRONT BUMPER                        | Deformed      | 2,850.00 FS              | *2,280.00 FS                   |
| 2                            | 2   |          | *FRONT BUMPER SIDE GUIDE -LH/RH      | Not Necessary | 654.00 FS                | *- FS                          |
| 3                            | 2   |          | *FRONT BUMPER UPPER SIDE GUIDE LH/RH | Not Necessary | 106.00 FS                | *- FS                          |
| 4                            | 2   |          | *FRONT BUMPER SUPPORT LH/RH          | Not Necessary | 96.00 FS                 | *- FS                          |
| 5                            | 1   |          | *AIR DUCT BRACKET                    | Not Necessary | 1,438.00 FS              | *- FS                          |
| 6                            | 1   |          | *RADIATOR GRILLE                     | Cracked       | 600.00 FS                | *480.00 FS                     |
| 7                            | 1   |          | *BONNET                              | Dented        | 3,300.00 FS              | *2,640.00 FS                   |
| 8                            | 1   |          | *BONNET LOGO                         | Necessary     | 181.00 FS                | *144.80 FS                     |
| 9                            | 1   |          | *FRONT BUMPER CENTER COVER           | Damaged       | 305.00 FS                | *244.00 FS                     |
| 10                           | 1   |          | *COOLANT INFO STICKER                | Necessary     | 71.00 FS                 | *56.80 FS                      |
| 11                           | 1   |          | *BONNET SEAL                         | Not Necessary | 135.00 FS                | *- FS                          |
| 12                           | 1   |          | *COVER OF CENTRE ENGINE COMPARTMENT  | Not Necessary | 375.00 FS                | *- FS                          |
| 13                           | 1   |          | *FRONT NO PLATE                      | Cracked       | 150.00 FS                | *80.00 FS                      |
| 14                           | 1   |          | *SUNDRIES                            | Not Necessary | 700.00 FS                | *- FS                          |
| F=Franchise part. S=SpcNett. |     |          |                                      |               |                          |                                |
|                              |     |          |                                      |               | <b>Total Parts (S\$)</b> | <b>10,961.00      5,925.60</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars  | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--|----------|-----------------|-----------------|
| <b>Labour Items</b>             |  |          |                 |                 |
| 1                               | TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS OUTSIDE TEMPERATURE SENSOR AND FRONT PARKING AID              | New      | 360.00          | 80.00           |
| 2                               | TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE   | New      | 350.00          | 0.00            |
| 3                               | TO DISMANTLE AND RENEW FRONT BUMPER ,BONNET AND RHS HEADLIGHT .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED | New      | 2,100.00        | 800.00          |
| 4                               | TO RESPRAY FRONT BUMPER AND BONNET   | New      | 1,850.00        | 800.00          |
| 5                               | TO SUPPLY AND RE-APPLY PAINT PROTECTION FILM   | New      | 2,100.00        | 2,100.00        |
| 6                               | TO SUPPLY AND RE-APPLY PAINT COATING   | New      | 400.00          | 400.00          |
| 7                               | TO CARRY OUT DIAGNOSTIC CHECK  | New      | 292.00          | 200.00          |
| <b>Gross Labour Cost (\$\$)</b> |  |          | <b>7,452.00</b> | <b>4,380.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >