

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070391/EMA3Q2**Date:** 14/01/2026**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7230081415
Claimant Vehicle No :	SHD6433D	Insured Vehicle No :	SLM1328M
Date of Loss:	25/07/2024	Nature of Claim:	TP
		Claim No:	5622796225SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6433D	Engine No:	2ZRS100566
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU203573401
Reg. Date:	01/11/2017 (Man. Year: 2017)	Odometer:	660619 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	GREENTRAC 6 mm	Rear Left Side:	GREENTRAC 6 mm
Front Right Side:	GREENTRAC 6 mm	Rear Right Side:	GREENTRAC 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,011.20	1,350.45	4,660.75	77.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,314.00	700.00	1,614.00	69.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,325.20	2,050.45	6,274.75	75.37
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	8,325.20	1,800.00	6,525.20	78.38
+ GST 9.00/9.00% (S\$)	749.27	162.00	587.27	78.38
Nett Amount (S\$)	9,074.47	1,962.00	7,112.47	78.38
+ Car Rental (5.0 x S\$87.20/day) (S\$)		436.00		
+ Loss of Earnings (5.0 x S\$50.00/day) (S\$)		250.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		2,650.18		
Global Sum Settlement (S\$)		2,650.00		

INSPECTION

Date of Assignment:	25/07/2024	STRIDES PREMIER AUTOMOTIVE SERVICES PTE LTD (HQ) 23 CHANGI SOUTH AVE 2 Singapore 486443
Date Inspected:	25/07/2024 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY ,FRONT DOOR LH (DISC 25%)	Dented	1,407.80 F	*1,055.85 F
2	1		*DOOR FRONT WINDOW REGULATOR SUB-ASSY ,LH (DISC 25%)	Bent	257.80 F	*193.35 F
3	1		*PANEL FRONT ARMREST BASE ,UPPER LH (DISC 25%)	Broken	55.00 F	*41.25 F
4	1		*STICKER LOGO (FRT DOOR) (SN)	Necessary	60.00 F	*60.00 F
5	1		*PILLAR FRONT BODY LH	Not Necessary	378.90 F	*- F
6	1		*WEATHERSTRIP FRONT DOOR LH	Not Necessary	250.70 F	*- F
7	1		*CHECK ASSY ,FRONT DOOR	Not Necessary	199.40 F	*- F
8	1		*DOOR FRONT MOTOR ASSY ,POWER WINDOW	Not Necessary	996.60 F	*- F
9	1		*DOOR FRONT WINDOW REGULATOR SUB-ASSY ,LH	Not Necessary	257.80 F	*- F
10	1		*HINGE ASSY ,FRONT DOOR LOWER LH	Not Necessary	120.00 F	*- F
11	1		*HINGE ASSY ,FRONT DOOR UPPER LH	Not Necessary	105.50 F	*- F
12	1		*MIRROR ASSY ,OUTER REAR VIEW LH	Not Necessary	1,454.40 F	*- F
13	1		*COVER ,OUTER MIRROR LH	Repair	117.80 F	*- F
14	1		*PILLAR ,CENTER BODY ,OUTER LH	Repair	349.50 F	*- F

F=Franchise part.

Total Parts (\$\$) 6,011.20 1,350.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	676.00	250.00
2	SPRAY PAINT	New	1,038.00	350.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	30.00
5	TO APPLY RUST- PROOFING ON AFFECTED AREA	New	200.00	20.00
6	TO TRANSFER DOOR MECHANISM	New	120.00	50.00
7	TO REPLACE SUNDRY PARTS	New	100.00	0.00
Gross Labour Cost (S\$)			2,314.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >