

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070392/UUA3Q2**Date:** 01/04/2025**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100407641
Claimant Vehicle No : SMQ868U **Insured Vehicle No :** SKS2866A
 Date of Loss: 23/07/2024 Nature of Claim: TP Claim No: 8661357721SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ868U**
 Make & Model: MERCEDES-BENZ E200, 2.0 EXCLUSIVE (R18 LED) (A) Engine No: 27492030927661
 Reg. Date: 31/03/2017 (Man. Year: 2016) Chassis No: WDD2130422A182020
 Colour: Brown Odometer: 131842 km
 Engine Capacity: 1991 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 275/40 R18
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	63,992.58	29,847.35	34,145.23	53.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,520.00	3,200.00	6,320.00	66.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	73,512.58	33,047.35	40,465.23	55.05
Approved Total (Overridden) (S\$)		26,000.00		
(S\$)	73,512.58	26,000.00	47,512.58	64.63
+ GST 9.00/9.00% (S\$)	6,616.13	2,340.00	4,276.13	64.63
Nett Amount (S\$)	80,128.71	28,340.00	51,788.71	64.63
+ Car Rental (18.0 x S\$120.00/day + 9.00% GST) (S\$)		2,354.40		
+ Doc/Search Fee (S\$)		27.25		
+ Other Costs (S\$)		130.00		
Nett Liability (S\$)		30,851.65		
Global Sum Settlement (S\$)		30,850.00		

INSPECTION

Date of Assignment: 25/07/2024
 Date Inspected: 25/07/2024 Inspected At: SPEEDWERKZ PTE LTD (Autobay) (HQ)
 1 KAKI BUKIT AVENUE 6 #01-73
 Singapore 417883
 Estimated Period of Repair: 15.0 days

Adjuster: MARCUS CHUA

Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Buckled	3,211.60 FL	*2,886.21 FL
2	1	*BONNET INSULATOR	Not Necessary	321.10 FL	*- FL
3	2	*BONNET SEAL L/R	Not Necessary	186.80 FL	*- FL
4	2	*BONNET UPPER LOCK L/R	Serviceable	168.20 FL	*- FL
5	2	*BONNET LOWER LOCK L/R	Twisted	648.80 FL	*648.80 FL
6	2	*BONNET SPRING L/R	Not Necessary	186.80 FL	*- FL
7	1	*BONNET OPENER	Not Necessary	179.30 FL	*- FL
8	2	*BONNET HINGE L/R	Bent	842.20 FL	*662.00 FL
9	2	*BONNET HINGE ACTUATOR L/R	Activated	622.60 FL	*622.60 FL
10	1	*BONNET STAR LOGO	Not Necessary	174.85 FL	*- FL
11	1	*RADIATOR GRILLE	Cracked	684.70 FL	*684.70 FL
12	1	*RADIATOR GRILLE OUTER CHROME }	Cracked	411.10 FL	*411.10 FL
13	1	*RADIATOR GRILLE STRIPE CHROME }		518.20 FL	*- FL
14	1	*RADIATOR GRILLE CAMERA	Serviceable	1,921.10 FL	*- FL
15	1	*RADIATOR GRILLE CAMERA BRACKET	Not Necessary	26.00 FL	*- FL
16	2	*HEADLAMP L/R	Cracked	8,266.20 FL	*7,041.60 FL
17	2	*HEADLAMP LOWER BRACKET	No such part	198.80 FL	*- FL
18	1	*FRONT BUMPER	Distorted	2,112.30 FL	*1,812.32 FL
19	1	*FRONT BUMPER SIDE RETAINER L/R	Not Necessary	255.60 FL	*- FL
20	1	*FRONT BUMPER TOW COVER	Not Necessary	96.00 FL	*- FL
21	1	*FRONT BUMPER NUMBER PLATE GARNISH	Deformed / Twisted	123.20 FL	*123.20 FL
22	2	*FRONT BUMPER SIDE GRILLE L/R	Twisted / Torn	486.80 FL	*486.80 FL
23	2	*FRONT BUMPER SIDE GRILLE CHROME L/R	Twisted	286.80 FL	*286.80 FL
24	1	*FRONT BUMPER LOWER CENTRE GRILLE	Torn	212.30 FL	*212.30 FL
25	1	*FRONT BUMPER LOWER CHROME	Scratched	255.60 FL	*255.60 FL
26	4	*FRONT BUMPER PARKING SENSOR	Serviceable	1,024.00 FL	*- FL
27	1	*SET FRONT BUMPER PARKING SENSOR BRACKET	Not Necessary	166.20 FL	*- FL
28	1	*FRONT BUMPER SPONGE	Torn	286.40 FL	*209.45 FL
29	1	*FRONT BUMPER REINFORCEMENT	Bent	855.70 FL	*802.35 FL
30	2	*FRONT BUMPER REINFORCEMENT BRACKET L/R	Bent	222.20 FL	*222.20 FL
31	1	*SUPPORT PANEL	Bent	1,541.10 FL	*607.80 FL
32	1	*CONDENSOR	Not Necessary	2,002.20 FL	*- FL
33	1	*RADIATOR	Not Necessary	1,601.60 FL	*- FL
34	1	*RADIATOR FAN MOTOR ASSY	Not Necessary	1,221.30 FL	*- FL
35	2	*FRONT FENDER L/R	Dented / Bent	2,956.20 FL	*2,244.00 FL
36	1	*FRONT FENDER FRONT SPLASH SHIELD L/R	N/S Torn	410.00 FL	*205.00 FL
37	2	*FRONT FENDER REAR SPLASH SHIELD L/R	Not Necessary	486.80 FL	*- FL
38	2	*FRONT HEAD REST L/R	Not Necessary	2,285.20 FL	*- FL
39	1	*SRS CONTROL UNIT	Not Necessary	1,605.20 FL	*- FL
40	2	*SRS SENSOR	Not Necessary	388.80 FL	*- FL
41	2	*FRONT SEATBELT L/R	Not Necessary	3,366.20 FL	*- FL
42	2	*REAR SEATBELT L/R	Not Necessary	1,288.80 FL	*- FL
43	1	*BOOTLID	Dented / Bent	3,112.30 FL	*2,980.21 FL
44	1	*BOOTLID LOGO	Necessary	77.80 FL	*77.80 FL
45	1	*BOOTLID E200 EMBLEM	Necessary	138.40 FL	*80.00 FL
46	1	*BOOTLID 9 G-TRONIC EMBLEM	Necessary	101.10 FL	*90.00 FL
47	2	*BOOTLID HINGE L/R	Not Necessary	516.20 FL	*- FL
48	2	*BOOTLID NUMBER PLATE LAMP L/R	Not Necessary	98.60 FL	*- FL
49	1	*BOOTLID OUTER CHROME	Not Necessary	200.10 FL	*- FL
50	1	*BOOTLID INNER TRIM	Not Necessary	386.80 FL	*- FL
51	1	*BOOTLID INNER LOCK	Not Necessary	424.30 FL	*- FL
52	1	*BOOTLID POWER CLOSING LOCK STRIKER	Not Necessary	511.70 FL	*- FL
53	1	*BOOTLID WEATHERSTRIP	Twisted	301.20 FL	*292.00 FL
54	2	*TAIL LAMP L/R	Cracked	1,936.40 FL	*1,430.00 FL
55	1	*REAR BUMPER LOWER	Distorted	396.70 FL	*303.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*REAR BUMPER LOWER CHROME	Distorted	411.40 FL	*411.40 FL
57	2		*REAR BUMPER LOWER CHROME L/R	No such part	385.20 FL	*- FL
58	1		*REAR BUMPER	Distorted	2,456.80 FL	*1,874.25 FL
			}			
59	1		*REAR BUMPER TOW COVER		96.00 FL	*- FL
			}			
60	1		*REAR BUMPER UNDER COVER	Torn	256.00 FL	*256.00 FL
61	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	186.80 FL	*- FL
62	2		*REAR BUMPER SIDE BRACKET L/R	Not Necessary	112.80 FL	*- FL
63	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	122.20 FL	*- FL
64	1		*REAR BUMPER REINFORCEMENT	Bent	1,113.10 FL	*871.25 FL
65	1		*REAR BUMPER CENTRE MOUNT BRACKET	Cracked	194.30 FL	*194.30 FL
66	4		*REAR BUMPER REVERSE SENSOR	Malfunction (2 PCS ONLY)	1,024.00 FL	*450.00 FL
67	1		*SET REAR BUMPER REVERSE SENSOR BRACKET	Necessary	166.20 FL	*166.20 FL
68	1		*REAR BUMPER SWITCH MODULE CODE A	Not Necessary	211.30 FL	*- FL
69	1		*REAR BUMPER SWITCH MODULE CODE B	Not Necessary	211.30 FL	*- FL
70	1		*REAR BUMPER SWITCH MODULE	Not Necessary	245.40 FL	*- FL
71	1		*REAR BUMPER SWITCH MODULE BRACKET	Not Necessary	101.00 FL	*- FL
72	1		*REAR BUMPER WIRE HARNESS	Not Necessary	601.30 FL	*- FL
73	1		*END PANEL	Dented / Bent	2,002.30 FL	*1,650.31 FL
74	1		*END PANEL GARNISH	Not Necessary	656.80 FL	*- FL
75	1		*SPARE TYRE PANEL WELL FIRBE	Cracked	714.20 FL	*511.00 FL
76	1		*SPARE TYRE PANEL	Repair	1,456.20 FL	*- FL
77	2		*REAR EXHAUST MUFFLER	Repair	2,621.40 FL	*- FL
78	1		*REAR EXHAUST TRIM BRACKET L/R	Torn	216.20 FL	*102.00 FL
79	1		*REAR EXHAUST CHROME TRIM L/R	N/S Serviceable / O/S Bent	989.60 FL	*399.00 FL
80	1		*REAR EXHAUST HEAT SHIELD	Bent	222.40 FL	*222.40 FL
81	1		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*40.00 FS
82	1		*FRONT BUMPER RIVET	Necessary	100.00 FS	*50.00 FS
83	1		*BONNET INSULATOR CLIPS	Not Necessary	80.00 FS	*- FS
84	1		*FRONT FENDER SPLASH SHIELD CLIPS	Necessary	220.00 FS	*40.00 FS
85	1		*COOLANT	Not Necessary	200.00 FS	*- FS
86	1		*FRONT NUMBER PLATE WITH HOLDER	Bent	70.00 FS	*40.00 FS
87	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*40.00 FS
88	1		*REAR BUMPER RIVET	Necessary	100.00 FS	*50.00 FS
89	1		*REAR BOOTLID C&C EMBLEM	Not Necessary	250.00 FS	*- FS
90	1		*REAR BOOTLID CHROME CLIPS	Not Necessary	30.00 FS	*- FS
91	1		*REAR BOOTLID TRIM CLIPS	Not Necessary	80.00 FS	*- FS
92	1		*END PANEL GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
93	1		*END PANEL SEALANT	Necessary	100.00 FS	*50.00 FS
94	1		*SPARE TYRE PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
95	1		*REAR FENDER TRIM L/R CLIPS	Not Necessary	180.00 FS	*- FS
96	1		*REAR NUMBER PLATE WITH GARNISH	Serviceable	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	70,900.65	33,125.95
- List Item Discount on L Items 10.00/10.00% (\$)	6,908.07	3,278.60
Total Parts (\$)	63,992.58	29,847.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT WIRING	New	50.00	20.00
2	TO REFIX FRONT PARKING SENSORS }	New	120.00	40.00
3	TO REFIX FRONT GRILLE CAMERA }	New	150.00	0.00
4	TO REMOVE AND REPLACE CONDESOR ,TOP UP GAS	New	200.00	0.00
5	TO REMOVE AND REPLACE RADIATOR AND CONDUCT WATER PRESSURE TEST	New	150.00	0.00
6	TO CHECK REAR WIRING	New	50.00	20.00
7	TO REPLACE REAR REVERSE SENSOR	New	120.00	30.00
8	TO REPLACE REAR REVERSE CAMERA	New	150.00	0.00
9	TO REMOVE AND TRANSFER BOOTLID FITTINGS TO NEW	New	250.00	60.00
10	TO REMOVE AND REFIT REAR INTERIOR TRIMS	New	200.00	60.00
11	TO PROVIDE LABOUR WORKMANSHIP	New	3,000.00	1,200.00
12	TO SPRAY PAINT ON AFFECTED PANELS	New	2,800.00	1,600.00
13	TO REPROGRAMME AND CALIBATE PARKING SENSORS & CAMERA	New	300.00	60.00
14	TO REPROGRAMME AND CALIBRATE SRS SYSTEM	New	500.00	0.00
15	TO REPROGRAMME HEADLAMPS	New	500.00	0.00
16	TO REPLACE AFFECTED SEATBELTS	New	250.00	0.00
17	TO REPLACE FRONT HEAD RESTS	New	200.00	0.00
18	RUST PROOFING	New	180.00	60.00
19	TO REMOVE AND REPLACE REAR EXHAUST MUFFLER	New	350.00	50.00
Gross Labour Cost (\$\$)			9,520.00	3,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >