

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24070397/KMA3Q2
Date: 12/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MCV0001886_03
Claimant Vehicle No : SNQ3185A Insured Vehicle No : GBK3219K
Date of Loss: 22/07/2024 Nature of Claim: TP Claim No: MCV2024D0008875

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNQ3185A
Make & Model: MERCEDES-BENZ E200 AMG LINE, 2.0 (R19 LED) (A) Engine No: 27492030739638
Reg. Date: 19/10/2016 (Man. Year: 2016) Chassis No: WDD2130422A053846
Colour: Metallic Dark Blue Odometer: 130753 km
Engine Capacity: 1991 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R19 Rear Tyre Size: 275/35Z R19
Front Left Side: Toyo 9 mm Rear Left Side: Fortune 9 mm
Front Right Side: Toyo 9 mm Rear Right Side: Fortune 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,712.50	34,825.00	3,887.50	10.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,010.00	3,760.00	3,250.00	46.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	45,722.50	38,585.00	7,137.50	15.61
Approved Total (Overridden) (S\$)		30,750.00		
(S\$)	45,722.50	30,750.00	14,972.50	32.75
+ GST 9.00/9.00% (S\$)	4,115.03	2,767.50	1,347.53	32.75
Nett Amount (S\$)	49,837.53	33,517.50	16,320.03	32.75
+ Loss of Use (12.0 x S\$100.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		33.18		
Nett Liability (S\$)		34,750.68		
Global Sum Settlement (S\$)		34,700.00		

INSPECTION

Date of Assignment: 26/07/2024
Date Inspected: 26/07/2024 Inspected At: Optima Werkz Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
Autopoint
Singapore 568047
Estimated Period of Repair: 12.0 days

Adjuster: KENNETH KONG

Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Feb 2025)
Parts:	143	MERCEDES-BENZ E200 AMG LINE 2.0 (R19 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNQ3185A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (WCP)	Bent	1,300.00 F	*1,300.00 F
2	1		*REAR BUMPER LOWER (WCP)	Bent / Cracked	380.00 F	*380.00 F
3	1		*REAR BUMPER LOWER MOULDING (WCP)	Cracked	300.00 F	*300.00 F
4	1		*REAR LH BUMPER REFLECTOR (WCP)	Cracked	40.00 F	*40.00 F
5	1		*REAR RH BUMPER REFLECTOR (WCP)	Serviceable	40.00 F	*- F
6	1		*REAR BUMPER CENTER BRACKET (WCP)	Distorted	120.00 F	*120.00 F
7	1		*REAR BUMPER LOWER INNER BRACKET (WCP)	Bent	140.00 F	*140.00 F
8	1		*REAR BOOT OPEN CONTROL MODULE (WCP)	Dented	280.00 F	*280.00 F
9	1		*REAR LH BUMPER RETAINER (WCP)	Serviceable	80.00 F	*- F
10	1		*REAR RH BUMPER RETAINER (WCP)	Serviceable	80.00 F	*- F
11	1		*REAR LH BUMPER SIDE SUPPORT BRACKET (WCP)	Cracked	75.00 F	*75.00 F
12	1		*REAR RH BUMPER SIDE SUPPORT BRACKET (WCP)	Cracked	75.00 F	*75.00 F
13	1		*REAR LH BUMPER UPPER BRACKET (WCP)	Distorted	50.00 F	*50.00 F
14	1		*REAR RH BUMPER UPPER BRACKET (WCP)	Distorted	50.00 F	*50.00 F
15	1		*REAR LH EXHAUST TAIL PIPE TIP (WCP)	Dented	340.00 F	*340.00 F
16	1		*REAR RH EXHAUST TAIL PIPE TIP (WCP)	Serviceable	340.00 F	*- F
17	1		*REAR BUMPER REINFORCEMENT (WCP)	Bent	760.00 F	*760.00 F
18	1		*REAR BUMPER TOWING COVER (WCP)	Serviceable	120.00 F	*- F
19	1		*REAR LH BUMPER LOWER SIDE TRIM (WCP)	Dented	95.00 F	*95.00 F
20	1		*TAILLAMP LH (WCP)	Cracked	520.00 F	*520.00 F
21	1		*TAILLAMP RH (WCP)	Mtg Cracked	520.00 F	*520.00 F
22	1		*REAR BOOT (WCP)	Bent	1,820.00 F	*1,820.00 F
23	1		*REAR BOOT MERCEDES LOGO (WCP)	Necessary	50.00 F	*50.00 F
24	1		*REAR BOOT E200 EMBLEM (WCP)	Necessary	130.00 F	*130.00 F
25	1		*REAR BOOT 9G-TRONIC EMBLEM (WCP)	Necessary	120.00 F	*120.00 F
26	1		*REAR BOOT OUTER CENTER CHROME MOULDING (WCP)	Cracked	180.00 F	*180.00 F
27	1		*REAR BOOT OUTER CHROME MOULDING LOWER GARNISH (WCP)	Distorted	220.00 F	*220.00 F
28	1		*REAR BOOT WEATHERSTRIP (\$210.00)(50%)	Distorted / Dented	231.00 FS	*105.00 FS
29	1		*REAR BOOT LOCK (WCP)	Dented	240.00 F	*240.00 F
30	1		*REAR BOOT INNER TRIM BOARD (WCP)	Serviceable	280.00 F	*- F
31	1		*REAR BOOT LOCK INNER TOP GARNISH (WCP)	Serviceable	130.00 F	*- F
32	1		*REAR LH BOOT HINGE COVER (WCP)	Cracked	35.00 F	*35.00 F
33	1		*REAR RH BOOT HINGE COVER (WCP)	Cracked	35.00 F	*35.00 F
34	1		*REAR BOOT OUTER OPENING SWITCH (WCP)	Dented	160.00 F	*160.00 F
35	2		*REAR LICENCE PLATE LAMP (WCP)	Serviceable	60.00 F	*- F
36	1		*REAR LH BOOT OPENING INNER GARNISH (WCP)	Serviceable	70.00 F	*- F
37	1		*REAR RH BOOT OPENING INNER GARNISH (WCP)	Serviceable	70.00 F	*- F
38	1		*REAR BOOT CLOSING DOWN LOCK LATCH ACTUATOR (WCP)	Jammed	375.00 F	*375.00 F
39	1		*REAR BOOT CLOSING DOWN LOCK LATCH ACTUATOR COVER (WCP)	Dented	65.00 F	*65.00 F
40	1		*REAR BOOT FLOOR BOARD (WCP)	Dented / Distorted	450.00 F	*450.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*REAR LUGGAGE COMPARTMENT INNER TRAY TOP COVER (WCP)	Cracked	330.00 F	*330.00 F
42	1		*REAR END PANEL (WCP)	Buckled	1,450.00 F	*1,450.00 F
43	1		*REAR END PANEL TRIM BOARD (WCP)	Mtg Cracked	150.00 F	*150.00 F
44	1		*REAR END FLOOR LOWER COVER (WCP)	Missing	120.00 F	*120.00 F
45	1		*FRONT BUMPER (WCP)	Buckled	1,380.00 F	*1,380.00 F
46	1		*FRONT BUMPER LICENCE PLATE MOULDING (WCP)	Cracked	130.00 F	*130.00 F
47	1		*FRONT LH BUMPER RETAINER (WCP)	Distorted	25.00 F	*25.00 F
48	1		*FRONT RH BUMPER RETAINER (WCP)	Serviceable	25.00 F	*- F
49	1		*FRONT LH BUMPER SIDE SUPPORT BRACKET (WCP)	Bent	100.00 F	*100.00 F
50	1		*FRONT RH BUMPER SIDE SUPPORT BRACKET (WCP)	Bent	100.00 F	*100.00 F
51	1		*FRONT BUMPER LOWER MOUNT BRACKET (WCP)	Distorted	180.00 F	*180.00 F
52	1		*FRONT BUMPER ENERGY ABSORBER (WCP)	Cracked	200.00 F	*200.00 F
53	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	480.00 F	*480.00 F
54	1		*FRONT BUMPER LOWER GRILLE COVER CHROME MOULDING (WCP)	Dented	400.00 F	*400.00 F
55	1		*FRONT BUMPER LOWER GRILLE COVER (WCP)	Serviceable	220.00 F	*- F
56	1		*FRONT LH BUMPER FOG LAMP GRILLE COVER (WCP)	Serviceable	140.00 F	*- F
57	1		*FRONT RH BUMPER FOG LAMP GRILLE COVER (WCP)	Serviceable	140.00 F	*- F
58	1		*FRONT RADAR SENSOR (WCP)	Dented	1,150.00 F	*1,150.00 F
59	5		*FRONT PARKING SENSOR (WCP)	Scratched / Shorted	750.00 F	*750.00 F
60	1		*FRONT BUMPER PEDESTRIAN PROTECTION PRESSURE SENSOR (WCP)	Shorted	180.00 F	*180.00 F
61	1		*RADIATOR GRILLE (WCP)	Cracked	250.00 F	*250.00 F
62	1		*RADIATOR GRILLE CHROME FRAME MOULDING (WCP)	Cracked	270.00 F	*270.00 F
63	1		*RADIATOR GRILLE OUTER TRIM (WCP)	Cracked	260.00 F	*260.00 F
64	1		*RADIATOR GRILLE OUTER TRIM MOULDING LH (WCP)	Scratched	80.00 F	*80.00 F
65	1		*RADIATOR GRILLE OUTER TRIM MOULDING RH (WCP)	Scratched	80.00 F	*80.00 F
66	1		*RADIATOR GRILLE EMBLEM (WCP)	Cracked	140.00 F	*140.00 F
67	1		*RADIATOR GRILLE EMBLEM BASE (WCP)	Cracked	100.00 F	*100.00 F
68	1		*RADIATOR GRILLE INNER AIR DUCT (WCP)	Dented	150.00 F	*150.00 F
69	1		*FRONT LH HEADLAMP (WCP)	Mtg Cracked	2,500.00 F	*2,500.00 F
70	1		*FRONT RH HEADLAMP (WCP)	Mtg Cracked	2,500.00 F	*2,500.00 F
71	1		*FRONT LH HEADLAMP MODULE (WCP)	Mtg Cracked	590.00 F	*590.00 F
72	1		*FRONT RH HEADLAMP MODULE (WCP)	Mtg Cracked	590.00 F	*590.00 F
73	1		*FRONT LH AIRBAG SENSOR (WCP)	Necessary	150.00 F	*150.00 F
74	1		*FRONT RH AIRBAG SENSOR (WCP)	Necessary	150.00 F	*150.00 F
75	1		*FRONT RADIATOR SUPPORT BAR WITH BRACKET (WCP)	Cracked	300.00 F	*300.00 F
76	1		*FRONT LH RADIATOR SUPPORT OUTER BRACKET (WCP)	Cracked	120.00 F	*120.00 F
77	1		*FRONT RH RADIATOR SUPPORT OUTER BRACKET (WCP)	Repair	120.00 F	*- F
78	1		*FRONT LH RADIATOR SUPPORT SIDE FRAME BRACKET (WCP)	Repair	110.00 F	*- F
79	1		*FRONT RH RADIATOR SUPPORT SIDE FRAME BRACKET (WCP)	Repair	110.00 F	*- F
80	1		*FRONT LH FENDER PANEL (WCP)	Repair	780.00 F	*- F
81	1		*FRONT LH SEAT BELT (WCP)	Jammed	1,300.00 F	*1,300.00 F
82	1		*FRONT RH SEAT BELT (WCP)	Jammed	1,300.00 F	*1,300.00 F
83	1		*REAR LH SEAT BELT (WCP)	Jammed	550.00 F	*550.00 F
84	1		*REAR RH SEAT BELT (WCP)	Jammed	550.00 F	*550.00 F
85	1		*AIRBAG CONTROLMODULE (WCP)	Necessary	860.00 F	*860.00 F
86	1		*FRONT RH FENDER PANEL (NPA)	Repair	0.00 F	*- F
87	1		*FRONT BONNET (NPA)	Repair	0.00 F	*- F
88	1		*FRONT LH DOOR PANEL(NPA)	Repair	0.00 F	*- F
89	1		*REAR LH FENDER PANEL (NPA)	Repair	0.00 F	*- F
90	1		*REAR RH FENDER PANEL (NPA)	Repair	0.00 F	*- F
91	1		*TAILLAMP PANEL LH (NPA)	Repair	0.00 F	*- F
92	1		*TAILLAMP PANEL RH (NPA)	Repair	0.00 F	*- F
93	1		*FRONT BUMPER CLIPS	Necessary	55.00 FS	*55.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
94	1		*FRONT BUMPER RIVETS	Necessary	50.00 FS	*50.00 FS
95	1		*FRONT FENDER LINER CLIPS	Not Necessary	50.00 FS	*- FS
96	1		*FRONT BUMPER LOWER COVER CLIPS	Necessary	50.00 FS	*50.00 FS
97	1		*FRONT LICENCE PLATE NUMBER WITH FRAME	Cracked	180.00 FS	*45.00 FS
98	1		*RADIATOR GRILLE CLIPS	Necessary	50.00 FS	*50.00 FS
99	1		*SET FRONT PARKING SENSOR MOUNTING BRACKET	Necessary	450.00 FS	*450.00 FS
100	1		*REAR BUMPER CLIPS	Necessary	55.00 FS	*55.00 FS
101	1		*REAR BUMPER LOWER COVER CLIPS	Necessary	50.00 FS	*50.00 FS
102	1		*REAR LICENCE PLATE NUMBER WITH FRAME	Serviceable	120.00 FS	*- FS
103	1		*REAR BOOT INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
104	1		*REAR END PANEL SEALANT	Necessary	180.00 FS	*30.00 FS
105	1		*TAILLAMP GUIDE CLIPS	Not Necessary	50.00 FS	*- FS
106	1		*SET REAR REVERSE SENSOR MOUNTING BRACKET	Necessary	450.00 FS	*450.00 FS
107	1		*REAR BOOT MOULDING CLIPS	Necessary	50.00 FS	*50.00 FS
108	5		*REAR REVERSE SENSOR	Damaged	900.00 F	*900.00 F
109	1		*REAR LH EXHAUST TAIL PIPE OUTER COVER	Dented	150.00 F	*150.00 F
110	1		*B PILLAR INNER LOWER TRIM LH	Mtg Cracked	240.00 F	*240.00 F
111	1		*FRONT RH SEAT BELT HEIGHT ADJUSTER	Cracked	220.00 F	*220.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	35,386.00	31,790.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	3,326.50	3,035.00
Total Parts (\$\$)	38,712.50	34,825.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST FRONT & REAR ACCIDENT AREAS & ETC	New	2,000.00	1,100.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOT ,REAR BUMPER ,REAR END PANEL ,REAR LH & RH FENDER ,TAILLAMP PANEL LH & RH ,FRONT BUMPER ,FRONT LH & RH FENDER PANEL ,FRONT BONNET ,FRONT LH DOOR ,ETC	New	3,000.00	1,600.00
3	TO REMOVE AND REFIT FRONT DRIVER ,PASSENGER SIDE AND REAR LUGGAGE COMPARTMENT INNER TRIMMINGS ,LININS ,COVER ,GARNISH AND OTHER NEW ITEMS TO REPLACE AIRBAG PARTS AND ENABLE BODYWORK REPAIR	New	450.00	250.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR BOOT INNER MECHANISM & ETC BACK TO ORIGINAL OPERATIONS	New	150.00	60.00
5	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER ,REVERSE SENSOR & ETC	New	100.00	60.00
6	LABOUR CHARGES TO REMOVE & REPLACE FRONT BUMPER PARKING SENSOR & ETC	New	100.00	60.00
7	TO TUFF KOTE & UNDERSEAL MATERIALS	New	160.00	60.00
8	TO DIAGNOSIS FAULT CODE AND RESET AIRBAG AND OTHER FAULT CODE	New	400.00	250.00
9	TO CHECK WIRING & ELECTRICAL SYSTEM	New	150.00	40.00
10	TO RECALIBRATE ,READJUST AND REALIGN HEADLAMP BEAM	New	200.00	100.00
11	TO RECALIBRATE RESET AND TEST FRONT CAMERA AND FRONT RADAR SENSOR	New	300.00	180.00
Gross Labour Cost (\$\$)			7,010.00	3,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >