



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SHD 7121Y

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	WING MIRROR RH	NOT NECESSARY	\$670.00	\$0.00
1	FRONT DOOR OUTER HANDLE RH	BROKEN	\$132.30	\$132.30
1	REAR DOOR RH	DENTED	\$2,201.10	\$2,201.10
	LESS 20.00% DISCOUNT		(\$600.68)	(\$466.68)
			\$2,402.72	\$1,866.72
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT DOOR COMFORTDELGRO RH (SN)	NECESSARY	\$75.00	\$75.00
1	REAR DOOR ZIG APPS RH (SN)	NECESSARY	\$80.00	\$80.00
			\$155.00	\$155.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING-REAR FENDER ARCH RH ETC		\$800.00	\$600.00
	SPRAY PAINTING-REAR BUMPER ETC		\$1,500.00	\$1,400.00
	TUFF KOTE		\$60.00	\$20.00
	TRANSFER OF DOORS		\$100.00	\$50.00
			\$2,460.00	\$2,070.00
GRAND TOTAL			\$5,017.72	\$4,091.72
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$3,250.00
Report Ref No: CS/AWA24070401/Enp3e2				

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.