



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO PC 7649C

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BONNET	TO REPAIR SEE LABOUR	\$1,180.00	\$0.00
1	FRONT BUMPER	DEFORMED	\$769.00	\$769.00
1	FRONT BUMPER FOGLAMP GARNISH LH	DEFORMED	\$106.00	\$106.00
2	FRONT BUMPER SIDE RETAINER L/R @\$151.80	N/S CRACKED	\$303.60	\$151.80
1	FRONT LH CORNER PANEL	DENTED	\$284.00	\$284.00
1	FRONT LH DOOR	TO REPAIR SEE LABOUR	\$2,245.00	\$0.00
1	FRONT LH DOOR SIDE MIRROR	CUT	\$980.00	\$750.00
1	FRONT LH HEADLAMP	CUT	\$805.00	\$805.00
1	FRONT LH STEP GARNISH	NOT NECESSARY	\$220.10	\$0.00
	LESS 25.00% DISCOUNT		(\$1,723.18)	(\$716.45)
			\$5,169.52	\$2,149.35

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	\$80.00	\$30.00
1	SET FRONT LH HEADLAMP CLIPS (SN)	NOT NECESSARY	\$25.00	\$0.00
			\$105.00	\$30.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING. (TO FR)		\$80.00	\$30.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT		\$1,200.00	\$700.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BONNET AND FRONT LH DOOR		\$700.00	\$300.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL		\$120.00	\$30.00
			\$2,100.00	\$1,060.00

GRAND TOTAL			\$7,374.52	\$3,239.35
--------------------	--	--	-------------------	-------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		\$2,500.00
Report Ref No: CS/INC24070403/Avh3			

TOTAL FOR SPARE PARTS: \$ 5,274.52 \$ 2,179.35
TOTAL FOR LABOUR : \$ 2,100.00 \$ 1,060.00
TOTAL REPAIR COST: \$ 7,374.52 \$ 3,239.35

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.