

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24070404/EPA3Q2
Date: 15/10/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0003403_02
Claimant Vehicle No : SMZ1934H Insured Vehicle No : SNN573Z
Date of Loss: 25/07/2024 Nature of Claim: TP Claim No: MFL2024D0008901

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMZ1934H
Make & Model: HONDA MOBILIO SV, 1.5 CVT (A) Engine No: L15Z12100720
Reg. Date: 26/08/2015 (Man. Year: 2015) Chassis No: MRHDD4870FP000169
Colour: Silver Odometer: 325614 km
Engine Capacity: 1497 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: KAPSEN 4 mm Rear Left Side: KAPSEN 4 mm
Front Right Side: KAPSEN 4 mm Rear Right Side: KAPSEN 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,832.00	2,351.20	4,480.80	65.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,730.00	960.00	1,770.00	64.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,562.00	3,311.20	6,250.80	65.37
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	9,562.00	2,600.00	6,962.00	72.81
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 26/07/2024
Date Inspected: 26/07/2024 Inspected At: SG Zoom Garage Pte Ltd (HQ)
53 Ubi Ave 1, #01-43 Paya Ubi Ind Pk
Singapore 408934
Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2024)
Parts:	M1-MPV	HONDA MOBILIO SV 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ1934H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	637.00 F	*- FL
2	2		*BONNET HINGE LH /RH	Not Necessary	100.00 F	*- FL
3	1		*HEADLAMP LH	Cut	1,363.00 F	*1,363.00 FL
4	1		*HEADLAMP BRACKET LH (NPA)	Not Necessary	0.00 F	*- FL
5	1		*FRONT GRILLE ASSY	Not Necessary	250.00 F	*- FL
6	1		*FRONT GRILLE GARNISH	Cut	241.00 F	*241.00 FL
7	1		*FRONT GRILLE HONDA EMBLEM BADGE	Not Necessary	50.00 F	*- FL
8	1		*RADIATOR ASSY	Not Necessary	1,100.00 F	*- FL
9	1		*AIRCON CONDENSER	Not Necessary	724.00 F	*- FL
10	1		*SUPPORT PANEL	Not Necessary	463.00 F	*- FL
11	1		*FRONT BUMPER	Broken	459.00 F	*459.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Bent	245.00 F	*245.00 FL
13	1		*FRONT BUMPER SPONGE (NPA)	Not Necessary	0.00 F	*- FL
14	2		*FRONT BUMPER SIDE RETAINER LH/RH	Broken	36.00 F	*36.00 FL
15	1		*FRONT BUMPER TOWING COVER	Missing	50.00 F	*50.00 FL
16	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	98.00 F	*- FL
17	1		*FRONT BUMPER FOG LAMP LH	Cut	261.00 F	*261.00 FL
18	1		*FRONT BUMPER FOG LAMP COVER LH	Cut	99.00 F	*99.00 FL
19	1		*FRONT BUMPER FOG LAMP COVER CHROME LH	Cut	45.00 F	*45.00 FL
20	18		*FRONT BUMPER CLIP	Necessary	90.00 F	*90.00 FL
21	1		*FRONT FENDER LH	Repair	343.00 F	*- FL
22	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	78.00 F	*- FL
23	12		*FRONT FENDER INNER SHIELD CLIPS LH	Not Necessary	60.00 F	*- FL
24	1		*FRONT NUMBER PLATE	Cut	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,832.00	2,929.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	577.80
Total Parts (\$\$)	6,832.00	2,351.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT AIR-CON CONDENSER ,RADIATOR AND REFILL AIRCON GAS	New	150.00	0.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	100.00	30.00
3	TO PANEL BEAT & STRAIGHTEN FRONT CHASSIS FRAME ,TO CUT & WELD SUPPORT PANEL INCLUDING REPLACEMENT OF PARTS & ALIGN WHERE NECESSARY TO REFIT & ADJUST THE SAME	New	1,200.00	300.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	600.00
5	TO RUST PROOFING OF THE AFFECTED AREAS	New	80.00	30.00
Gross Labour Cost (\$\$)			2,730.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >