

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estm: \_\_\_\_\_  
 OD / TP RES / CD RES / EVA / INV / MV  
 To in Vehicle NO: \_\_\_\_\_  
 at W/O m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: 5ME7596X Yr Regn: 2018, Oct.  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or  
 Make: Toyota Noah Hybrid CC: 1797  
 Colour: Grey A/C: Insured / Std / NI / NA  
 Sp. Reading: 62108 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
 C/No: ZWR800328939

Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195/65R15  
 R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front Rear  
 R/Bal. 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 25/07/24

Survey held at JL Perfect  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                    |
|-------------|-----------------------------------------|
|             | <u>TP 1st Cap</u>                       |
|             | <u>COE Expiry</u>                       |
|             | <u>Estimate given during 1st Survey</u> |
|             | <u>MV: 106K</u>                         |
|             | <u>PV: 32.5K</u>                        |
|             | <u>Nett: 73.5K</u>                      |
|             | <u>243A.</u>                            |

Date/Time, File Pass to? ☐ : Preli. Report  
☐ : Final Report

1) Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Inve (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

3 + RS. \$1 \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

Report Format: \_\_\_\_\_

Report Form: \_\_\_\_\_

# JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778  
E-mail:jlperfectautowork@gmail.com



DATE : 24.07.2024

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS  
VEHICLE NO : **SME7596X**  
MODEL : **TOYOTA NOAH**  
DATE OF ACCIDENT : 24.07.2024  
TIME OF ACCIDENT : 07:40 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                                        | QTY | UNIT LIST PRICE | TOTAL LIST PRICE                 |
|-----|----------------------------------------------------|-----|-----------------|----------------------------------|
| 1   | REAR BUMPER <i>Distorted x</i>                     | 1   | \$ 1,339.31     | \$ <u>1,339.31</u> <i>985</i>    |
| 2   | REAR BUMPER TOW HOOK COVER <i>Missing</i>          | 1   | \$ 28.10        | \$ 28.10 <i>✓</i>                |
| 3   | REAR BUMPER REFLECTOR <i>LH angled</i>             | 2   | \$ 125.60       | \$ 251.20 <i>25.80</i>           |
| 4   | REAR BUMPER SIDE RETAINER (FRONT) <i>new</i>       | 2   | \$ 145.80       | \$ 291.60 <i>+</i>               |
| 5   | TAILGATE <i>Distorted</i>                          | 1   | \$ 1,812.70     | \$ 1,812.70 <i>✓</i>             |
| 6   | TAILGATE DAMPER <i>new</i>                         | 2   | \$ 286.00       | \$ 572.00 <i>+</i>               |
| 7   | TAILGATE OUTER MOULDING <i>angled</i>              | 1   | \$ 767.80       | \$ <u>767.80</u> <i>+</i>        |
| 8   | TAILGATE NUMBER PLATE LAMP <i>new</i>              | 2   | \$ 65.40        | \$ 130.80 <i>+</i>               |
| 9   | TAIL GATE LOGO <i>new</i>                          | 1   | \$ 78.00        | \$ 78.00 <i>+</i>                |
| 10  | TAIL GATE EMBLEM 'HYBRID SYNERGY DRIVE' <i>New</i> | 1   | \$ 75.20        | \$ 75.20 <i>✓</i>                |
| 11  | TAILGATE STOPPER <i>new</i>                        | 2   | \$ 28.60        | \$ 57.20 <i>+</i>                |
| 12  | TAILGATE INNER LOCK <i>Damaged</i>                 | 1   | \$ 452.10       | \$ <u>452.10</u> <i>+</i>        |
| 13  | TAILGATE LOWER LOCK <i>new</i>                     | 1   | \$ 36.70        | \$ 36.70 <i>+</i>                |
| 14  | TAILGATE DETECTOR <i>angled</i>                    | 1   | \$ 175.20       | \$ 175.20 <i>✓</i>               |
| 15  | TAILGATE DETECTOR WIRE HARNESS <i>new</i>          | 1   | \$ 287.30       | \$ 287.30 <i>✓</i>               |
| 16  | TAILGATE INNER TRIM <i>angled</i>                  | 1   | \$ 580.30       | \$ 580.30 <i>✓</i>               |
| 17  | TAILGATE INNER HOLDER <i>Deformed</i>              | 1   | \$ 65.00        | \$ 65.00 <i>✓</i>                |
| 18  | TAILGATE SIDE INNER TRIM <i>new</i>                | 2   | \$ 460.10       | \$ 920.20 <i>+</i>               |
| 19  | TAILGATE WEATHER STRIP <i>cut</i>                  | 1   | \$ 375.10       | \$ 375.10 <i>✓</i>               |
| 20  | TAILGATE WINDSCREEN GLASS C/W MOULDING <i>new</i>  | 1   | \$ 1,198.70     | \$ 1,198.70 <i>✓</i>             |
| 21  | TAIL LAMP <i>new LH cut</i>                        | 2   | \$ 853.30       | \$ <u>1,706.60</u> <i>853.30</i> |
| 22  | TAIL LAMP OUTER PANEL <i>new</i>                   | 2   | \$ 311.10       | \$ 622.20 <i>+</i>               |



TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SME7596X**  
 MODEL : **TOYOTA NOAH**  
 DATE OF ACCIDENT : 24.07.2024  
 TIME OF ACCIDENT : 07:40 HOURS

|    |                                                     |   |             |             |        |
|----|-----------------------------------------------------|---|-------------|-------------|--------|
| 23 | TAIL LAMP INNER PANEL <i>new</i>                    | 2 | \$ 398.10   | \$ 796.20   | +      |
| 24 | TAIL LAMP LOWER GARNISH LH <i>torn</i>              | 1 | \$ 178.80   | \$ 178.80   | ✓      |
| 25 | TAIL LAMP LOWER GARNISH RETAINER <i>new</i>         | 2 | \$ 160.70   | \$ 321.40   | +      |
| 26 | TAIL LAMP INNER LOWER PANEL <i>new</i>              | 2 | \$ 376.20   | \$ 752.40   | +      |
| 27 | REAR FENDER INNER TRIM <i>Lit cracked</i>           | 2 | \$ 906.51   | \$ 1,813.02 | 906.51 |
| 28 | REAR FENDER COWLING <i>new</i>                      | 2 | \$ 118.70   | \$ 237.40   | +      |
| 29 | REAR END PANEL C/W END EXTEND PANEL <i>Dented</i>   | 1 | \$ 762.20   | \$ 762.20   | ✓      |
| 30 | REAR END PANEL TOP GARNISH <i>2 dented</i>          | 1 | \$ 168.20   | \$ 168.20   | ✓      |
| 31 | REAR FLOOR PANEL <i>Repair</i>                      | 1 | \$ 980.00   | \$ 980.00   | +      |
| 32 | REAR FLOOR MAT <i>new torn</i>                      | 1 | \$ 685.10   | \$ 685.10   | ✓      |
| 33 | REAR FLOOR PANEL TOP BOARD <i>torn</i>              | 1 | \$ 1,165.50 | \$ 1,165.50 | +      |
| 34 | REAR FLOOR PANEL TOP BOARD INNER SUPPORT <i>new</i> | 1 | \$ 469.30   | \$ 469.30   | +      |
| 35 | JACK COVER GARNISH <i>gap</i>                       | 1 | \$ 186.00   | \$ 186.00   | +      |
| 36 | BATTERY COVER GARNISH <i>gap</i>                    | 1 | \$ 240.00   | \$ 240.00   | +      |

TOTAL PRICE \$ 20,578.83  
 LESS 25% \$ 5,144.71  
**SUB TOTAL PRICE \$ 15,434.12**

**SPECIAL NETT ITEMS**

| S/N | DESCRIPTION                                    | QTY | UNIT S/NETT | TOTAL S/NETT |    |
|-----|------------------------------------------------|-----|-------------|--------------|----|
| 1   | REAR NUMBER PLATE <i>new</i>                   | 1   | \$ 80.00    | \$ 80.00     | +  |
| 2   | REAR BUMPER CLIPS (SET) <i>new</i>             | 1   | \$ 80.00    | \$ 80.00     | 30 |
| 3   | TAIL LAMP CLIP (SET) <i>new</i>                | 1   | \$ 60.00    | \$ 60.00     | +  |
| 4   | TAIL LAMP LOWER GARNISH CLIP (SET) <i>new</i>  | 1   | \$ 60.00    | \$ 60.00     | 20 |
| 5   | TAIL LAMP INNER LOWER PANEL SEALANT <i>new</i> | 2   | \$ 80.00    | \$ 160.00    | +  |
| 6   | TAILGATE OUTER MOULDING CLIP (SET) <i>new</i>  | 1   | \$ 40.00    | \$ 40.00     | 20 |
| 7   | TAILGATE INNER TRIM CLIP (SET) <i>new</i>      | 1   | \$ 80.00    | \$ 80.00     | 30 |
| 8   | TAILGATE TOP INNER TRIM CLIP (SET) <i>new</i>  | 1   | \$ 50.00    | \$ 50.00     | +  |
| 9   | TAILGATE SIDE INNER TRIM CLIP (SET) <i>new</i> | 1   | \$ 50.00    | \$ 50.00     | +  |
| 10  | TAILGATE WINDSCREEN SEALANT <i>2 files</i>     | 1   | \$ 80.00    | \$ 80.00     | 40 |
| 11  | TAILGATE WINDSCREEN INNER SEAL <i>1</i>        | 1   | \$ 60.00    | \$ 60.00     | 30 |
| 12  | TAILGATE WINDSCREEN SOLAR FILM <i>new</i>      | 1   | \$ 550.00   | \$ 550.00    | +  |
| 13  | PRIVATE HIRE DECAL <i>new</i>                  | 1   | \$ 80.00    | \$ 80.00     | +  |
| 14  | REAR FENDER INNER TRIM CLIP (SET) <i>new</i>   | 1   | \$ 80.00    | \$ 80.00     | 30 |

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SME7596X**  
 MODEL : **TOYOTA NOAH**  
 DATE OF ACCIDENT : 24.07.2024  
 TIME OF ACCIDENT : 07:40 HOURS

|    |                                                   |   |           |                      |           |
|----|---------------------------------------------------|---|-----------|----------------------|-----------|
| 15 | REAR FENDER INNER COWLING CLIP (SET) <i>new</i>   | 1 | \$ 80.00  | \$ 80.00             | <i>+</i>  |
| 16 | REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i> | 1 | \$ 40.00  | \$ <del>40.00</del>  | <i>20</i> |
| 17 | REAR END PANEL INSULATION SEAL <i>new</i>         | 1 | \$ 150.00 | \$ <del>150.00</del> | <i>60</i> |
| 18 | REAR FLOOR PANEL INSULATION SEAL <i>new</i>       | 1 | \$ 350.00 | \$ 350.00            | <i>+</i>  |
| 19 | JACK COVER GARNISH CLIP (SET) <i>new</i>          | 1 | \$ 50.00  | \$ 50.00             | <i>+</i>  |
| 20 | JACK <i>3rd</i>                                   | 1 | \$ 150.00 | \$ 150.00            | <i>+</i>  |
| 21 | BATTERY <i>new</i>                                | 1 | \$ 450.00 | \$ 450.00            | <i>+</i>  |
| 22 | BATTERY COVER GARNISH CLIP (SET) <i>new</i>       | 1 | \$ 50.00  | \$ 50.00             | <i>+</i>  |
| 23 | REVERSE CAMERA <i>new</i>                         | 1 | \$ 450.00 | \$ 450.00            | <i>+</i>  |
| 24 | REVERSE SENSOR (2PCS) <i>new</i>                  | 1 | \$ 250.00 | \$ <del>250.00</del> | <i>20</i> |

**TOTAL \$ 3,530.00**

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

| S/N | JOB DESCRIPTION                                                              | PRICE                  | ADJUSTED COST |
|-----|------------------------------------------------------------------------------|------------------------|---------------|
| 1   | PANEL BEATING, REMOVAL AND REPLACING PARTS                                   | \$ <del>2,800.00</del> | <i>700</i>    |
| 2   | TO SPRAY PAINT AFFECTED AREA                                                 | \$ <del>1,800.00</del> | <i>700</i>    |
| 3   | TUFF COAT                                                                    | \$ <del>250.00</del>   | <i>60</i>     |
| 4   | REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR | \$ <del>180.00</del>   | <i>60</i>     |
| 5   | REMOVE AND REFIX REAR AIRCON BLOWER MOTOR                                    | \$ 350.00              | <i>X</i>      |
| 6   | REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING                         | \$ <del>80.00</del>    | <i>50</i>     |
| 7   | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING                         | \$ <del>80.00</del>    | <i>50</i>     |
| 8   | REAR CHASSIS ALIGNMENT                                                       | \$ 250.00              | <i>X</i>      |
| 9   | REMOVE AND REFIX TAILGATE WINDSCREEN                                         | \$ <del>150.00</del>   | <i>120</i>    |



TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SME7596X**  
 MODEL : **TOYOTA NOAH**  
 DATE OF ACCIDENT : 24.07.2024  
 TIME OF ACCIDENT : 07:40 HOURS

|    |                                                                                                |           |    |
|----|------------------------------------------------------------------------------------------------|-----------|----|
| 10 | TRANSFER TAILGATE MECHANISM                                                                    | \$ 120.00 | 60 |
| 11 | CONDUCT WATER LEAKAGE TEST                                                                     | \$ 100.00 | X  |
| 12 | REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT                               | \$ 80.00  | X  |
| 13 | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC. | \$ 180.00 | X  |

**TOTAL \$ 6,420.00**

TOTAL PARTS COST : \$ 18,964.12  
 TOTAL LABOUR COST : \$ 6,420.00  
 TOTAL REPAIR COST : \$ 25,384.12

*Adrian Lij*  
*2/8 25/07/24*  
*06 Days*

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

**PARTS PRICES ARE SUBJECT TO CHANGES.**

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
 IRENE  
 HP : 8297 9787

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: