

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS24070413/ANP3M4**Date:** 21/10/2024**REFERENCE**

Handling Insurer: ECICS Limited Policy No: MPC24P00106700  
**Claimant Vehicle No :** SLT5933C **Insured Vehicle No :** SNR2929Y  
Date of Loss: 25/07/2024 Nature of Claim: TP Claim No: DMPC2400954H/ST

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLT5933C**  
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN045583  
Reg. Date: 01/11/2017 (Man. Year: 2017) Chassis No: WAUZZZF44JA025228  
Colour: Black Odometer: 143701 km  
Engine Capacity: 1395 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/45R18 Rear Tyre Size: 225/45R18  
Front Left Side: 6 mm Rear Left Side: 6 mm  
Front Right Side: 6 mm Rear Right Side: 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,757.50	4,989.60	3,767.90	43.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	1,060.00	870.00	45.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,687.50</b>	<b>6,049.60</b>	<b>4,637.90</b>	<b>43.40</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,800.00</b>		
<b>(S\$)</b>	10,687.50	4,800.00	5,887.50	55.09
<b>+ GST 9.00/9.00% (S\$)</b>	961.88	432.00	529.88	55.09
<b>Nett Amount (S\$)</b>	<b>11,649.38</b>	<b>5,232.00</b>	<b>6,417.38</b>	<b>55.09</b>

**INSPECTION**

Date of Assignment: 25/07/2024  
Date Inspected: 26/07/2024 Inspected At: TWINCAR AUTOMOTIVE PTE LTD (KAKI BUKIT)  
#01-17 KAKI BUKIT AUTOHUB  
SINGAPORE 417921  
Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2024)
Parts:	143	AUDI A4 1.4 TFSI S TRONIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT5933C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	1,790.00 FL	*1,790.00 FL
2	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	396.00 FL	*- FL
3	1		*REAR LH CONTROL ARM (1)	Bent	405.00 FL	*405.00 FL
4	1		*REAR LH CONTROL ARM (2)	Not Necessary	405.00 FL	*- FL
5	1		*REAR LH FENDER	Repair	1,800.00 FL	*- FL
6	1		*REAR LH KNUCKLE ARM	Damaged	869.00 FL	*869.00 FL
7	1		*REAR LH KNUCKLE ARM BEARING	Damaged	765.00 FL	*765.00 FL
8	1		*REAR LH LOWER ARM	Bent	515.00 FL	*515.00 FL
9	1		*REAR LH SHOCK ABSORBER	Not Necessary	405.00 FL	*- FL
10	1		*REAR LH UPPER ARM	Not Necessary	425.00 FL	*- FL
11	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
12	1		*REAR LH SPORT RIM	Cut	1,080.00 FS	*800.00 FS
13	1		*REAR LH TYRE (225/45ZR18)	Cut	600.00 FS	*250.00 FS
					<b>Sub Total (\$\$)</b>	<b>9,535.00      5,424.00</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>777.50      434.40</b>
					<b>Total Parts (\$\$)</b>	<b>8,757.50      4,989.60</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	50.00
2	TO REMOVE, CHANGE REAR SUSPENSION PARTS, AXLE CARRIAGE, ABSORBER, LOWER ARM, TOP ARM, TRAILING ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB AND ETC	New	350.00	200.00
3	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM	New	100.00	80.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	700.00	400.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	600.00	300.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,930.00</b>	<b>1,060.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >