

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. : SAC2400656

INV Date : 19-09-2024

Reference CD/LPC24070415/Uma3

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBD 8921U
Insured Veh. YN 5230A
Claim No. 24/24/24/VC05/029574
Policy No. Z24VC05023791
Accident Date 21/07/2024
Inspection Date 30/07/2024

Description	Amount
Third Party Express Settlement	450.00
Sub-Total	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CD/LPC24070415/Uma3
300 BEACH ROAD	Date:	19/09/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	YN 5230A	Veh. Inspected	GBD 8921U
Policy No.	Z24VC05023791	Coverage	0
Claim No.	24/24/24/VC05/029574	Excess	\$0.00
Assign From	ENG HUEY NI	Assign Date	26/07/2024

2. Vehicle Details

Make & Model	TOYOTA DYNA	C.C	2982
Engine No.	1KD2495237	Year of Reg.	26/06/2015
Chassis No.	JTFAT35Y10K204569	Colour	WHITE
Odometer	176135 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15	BRIDGESTONE	6
L/H Front Tyre	195R15	BRIDGESTONE	6
R/H Rear Tyre	155R12	FALKEN	6
L/H Rear Tyre	155R12	FALKEN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/07/2024	Inspection Date	30/07/2024
Survey held at	CARSMITH PTE LTD 13 KAKI BUKIT ROAD 4 #01-20 BARTLEY BIZ CENTRE		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBD 8921U

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	TAILGATE	DENTED /BENT	\$1,365.00	\$1,365.00
1	TAILGATE FLOOR PANEL	TO REPAIR SEE LABOUR	\$987.00	\$0.00
1	SIDE GATE LH	TO REPAIR SEE LABOUR	\$1,850.00	\$0.00
1	SIDE GATE LOCK LH	NOT NECESSARY	\$280.00	\$0.00
1	SIDE GATE FLOOR PANEL LH	NOT NECESSARY	\$3,258.00	\$0.00
1	REAR TAIL LAMP LH	NOT NECESSARY	\$640.00	\$0.00
1	REAR TAIL LAMP PANEL LH	NOT NECESSARY	\$270.00	\$0.00
1	NUMBER PLATE PANEL	NOT NECESSARY	\$490.00	\$0.00
1	END STEP PANEL	BENT	\$450.00	\$450.00
1	END PANEL	TO REPAIR SEE LABOUR	\$980.00	\$0.00
2	END PANEL SIDE BRACKET LH & RH	NOT NECESSARY	\$560.00	\$0.00
2	END PANEL SIDE BRACKET STOPPER LH & RH	NOT NECESSARY	\$122.00	\$0.00
	LESS 25.00% DISCOUNT		(\$2,813.00)	(\$453.75)
			\$8,439.00	\$1,361.25

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE (SN)	SERVICEABLE	\$90.00	\$0.00
1	70KM/H STICKER (SN)	NECESSARY	\$35.00	\$10.00
1	13 PAX STICKER (SN)	NECESSARY	\$35.00	\$10.00
1	TOYOTA STICKER (SN)	NOT FITTED	\$55.00	\$0.00
1	DYNA STICKER	NOT FITTED	\$35.00	\$0.00
1	SET TAILGATE INNER ALUMINIUM PLATE (SN)	BENT	\$480.00	\$400.00
1	SET REAR CHECKED PLATE RIVETS (SN)	NECESSARY	\$180.00	\$30.00
1	JOINT SEALANT (SN)	NOT NECESSARY	\$120.00	\$0.00
			\$1,030.00	\$450.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	CHECK REAR WIRING AND LIGHTING SYSTEM		\$100.00	\$20.00
	REMOVE AND RENEW REAR REVERSE SENSOR	NOT NECESSARY	\$120.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE AND REFIT REAR LINING ,TRIM AND GARNISH	NOT NECESSARY	\$150.00	\$0.00
	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE FLOOR PANEL,SIDE GATE LH AND END PANEL.		\$1,200.00	\$400.00
	SPRAY PAINTING ON AFFECTED AREAS		\$1,000.00	\$500.00
	APPLY ANTI RUST ON AFFECTED AREAS		\$100.00	\$30.00
			\$2,670.00	\$950.00
GRAND TOTAL			\$12,139.00	\$2,761.25
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$2,200.00
Report Ref No: CD/LPC24070415/Uma3				

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 1 of 15)

PHOTOGRAPHS FOR VEHICLE NO. : GBD 8921U



PHOTOGRAPHS FOR VEHICLE NO. : GBD 8921U



PHOTOGRAPHS FOR VEHICLE NO. : GBD 8921U



PHOTOGRAPHS FOR VEHICLE NO. : GBD 8921U



PHOTOGRAPHS FOR VEHICLE NO. : GBD 8921U



PHOTOGRAPHS FOR VEHICLE NO. : GBD 8921U




PHOTOGRAPHS FOR VEHICLE NO. : GBD 8921U



PHOTOGRAPHS FOR VEHICLE NO. : GBD 8921U



PHOTOGRAPHS FOR VEHICLE NO. : GBD 8921U







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 10 of 15)

PHOTOGRAPHS FOR VEHICLE NO. : GBD 8921U




PHOTOGRAPHS FOR VEHICLE NO. : GBD 8921U



PHOTOGRAPHS FOR VEHICLE NO. : GBD 8921U



PHOTOGRAPHS FOR VEHICLE NO. : GBD 8921U



PHOTOGRAPHS FOR VEHICLE NO. : GBD 8921U



PHOTOGRAPHS FOR VEHICLE NO. : GBD 8921U







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : GBD 8921U





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : GBD 8921U



PHOTOGRAPHS FOR VEHICLE NO. : GBD 8921U





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : GBD 8921U

