

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI24070416/EVP3M4**Date:** 13/08/2024**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MAA00601
<b>Claimant Vehicle No :</b>	SHA8018Y	<b>Insured Vehicle No :</b>	SNN5488D
Date of Loss:	24/07/2024	Nature of Claim:	TP Claim No: M2404152

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHA8018Y</b>		
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Engine No:	G4LEPUR01867
Reg. Date:	28/07/2021 (Man. Year: 2019)	Chassis No:	KMHC851CVLU183116
Colour:	Yellow	Odometer:	432661 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

**CONDITION OF TYRES**

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,113.36	0.00	1,113.36	100.00
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	240.00	160.00	80.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,365.36</b>	<b>172.00</b>	<b>1,193.36</b>	<b>87.40</b>
<b>+ GST 9.00/9.00% (S\$)</b>	<b>122.88</b>	<b>15.48</b>	<b>107.40</b>	<b>87.40</b>
<b>Nett Amount (S\$)</b>	<b>1,488.24</b>	<b>187.48</b>	<b>1,300.76</b>	<b>87.40</b>

**INSPECTION**

Date of Assignment:	25/07/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang) COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969
Date Inspected:	26/07/2024	Inspected At:	
Estimated Period of Repair:	1.0 days		

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Aug 2024)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA8018Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE MIRROR ASSY LH	Repair	1,391.70 FL	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	1,391.70 0.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	278.34 0.00
					Total Parts (S\$)	1,113.36 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	120.00	80.00
2	SPRAYPAINT	New	120.00	80.00
Gross Labour Cost (\$\$)			240.00	160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >