

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III24070418/ANH3Q2  
Date: 23/12/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL003256\_04  
Claimant Vehicle No : GBG9434L Insured Vehicle No : PC8709G  
Date of Loss: 23/07/2024 Nature of Claim: TP Claim No: MFL2024D0008770

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBG9434L  
Make & Model: ADIVA AD1 200, 190cc 3W Engine No: K9KC400D057762  
Reg. Date: 08/12/2017 (Man. Year: 2017) Chassis No: VSKYBAM20Z0149435  
Colour: White Odometer: 165676 km  
Engine Capacity: 1461 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,958.29	3,358.97	4,599.32	57.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,660.00	1,660.00	2,000.00	54.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,618.29	5,018.97	6,599.32	56.80
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	11,618.29	4,000.00	7,618.29	65.57
+ GST 9.00/9.00% (S\$)	1,045.65	360.00	685.65	65.57
Nett Amount (S\$)	12,663.94	4,360.00	8,303.94	65.57

INSPECTION

Date of Assignment: 25/07/2024  
Date Inspected: 26/07/2024 Inspected At: A-Tec Automotive Pte Ltd (Kaki Bukit)  
8 Kaki Bukit Ave 4, #04-20 Premier  
Singapore 415875  
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

We have checked and confirmed that all part prices are correct. The actual work carried out and listed as labour and spray painting is accurate, and the fees charged for labour and spray painting are correct.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 23 Dec 2025)	
<b>Parts:</b>	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBG9434L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Not Necessary	1,553.70 FL	*- FL
2	2		*REAR DOOR HINGES	Not Necessary	199.20 FL	*- FL
3	1		*REAR DOOR INNER TRIM	Not Necessary	125.00 FL	*- FL
4	1		*REAR DOOR LOCK	Not Necessary	155.00 FL	*- FL
5	1		*REAR DOOR RUBBER	Not Necessary	145.00 FL	*- FL
6	1		*REAR DOOR LH	Dented	1,584.90 FL	*1,584.90 FL
7	1		*REAR DOOR INNER TRIM	Not Necessary	125.10 FL	*- FL
8	1		*REAR DOOR LOCK	Damaged	155.00 FL	*155.00 FL
9	1		*REAR DOOR OUTER GARNISH	Not Necessary	351.50 FL	*- FL
10	1		*REAR DOOR RUBBER	Not Necessary	145.00 FL	*- FL
11	2		*REAR DOOR HINGES	Not Necessary	199.20 FL	*- FL
12	1		*REAR TAILLAMPS	N/S Cracked	569.60 FL	*284.80 FL
13	1		*REAR END PANEL	Dented	1,355.70 FL	*485.00 FL
14	1		*REAR END PANEL INNER GARNISH	Deformed	125.00 FL	*125.00 FL
15	1		*REAR BUMPER	Deformed	624.80 FL	*624.80 FL
16	1		*REAR BUMPER INNER SPONGE	Cracked	133.80 FL	*133.80 FL
17	2		*REAR BUMPER REFLECTORS	Not Necessary	130.00 FL	*- FL
18	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	200.60 FL	*- FL
19	1		*COMPANY STICKER	Not Necessary	280.00 FS	*- FS
20	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
21	1		*REAR DOOR GLASS INNER SEAL RH	Not Necessary	85.00 FS	*- FS
22	1		*REAR DOOR GLASS INNER SEAL LH	Necessary	85.00 FS	*60.00 FS
23	1		*REAR DOOR 70KM/H STICKER	Necessary	28.00 FS	*15.00 FS
24	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS
25	1		*SET REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,746.10</b>	<b>3,698.30</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	787.81	339.33
<b>Total Parts (\$\$)</b>	<b>7,958.29</b>	<b>3,358.97</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,REFIT REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES ,INNER TRIM TO ASSIST REPAIR	New	150.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	50.00
4	TO TRANSFER REAR DOORS MECHANISM AND WIRING ASSEMBLY TO ASSIST REPAIR	New	80.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	100.00
6	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	150.00	60.00
7	TO PROVIDE LABOUR CHARGES ,WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS ,REPAIR INCLUDING CUT AND WELD REALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,500.00	600.00
8	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHARGED BODY PARTS ,REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	1,400.00	700.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,660.00</b>	<b>1,660.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >