



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD  
16 RAFFLES QUAY  
#42-01 HONG LEONG BUILDING  
SINGAPORE 048581

Ref: CS/FCI24070423/Unp3

Date: 26/07/2024

Code: FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 7300Y	Veh. Inspected	SJK 5471P
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24006475MFCT	Excess	\$0.00
Assign From	BETTY	Assign Date	26/07/2024

### 2. Vehicle Details

Make & Model	HONDA STREAM (A)	C.C	1799
Engine No.	R18A1760088	Year of Reg.	24/10/2008
Chassis No.	RN61053639	Colour	RED
Odometer	466253 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55R16	HANKOOK	6
L/H Front Tyre	205/55R16	HANKOOK	6
R/H Rear Tyre	205/55R16	HANKOOK	6
L/H Rear Tyre	205/55R16	HANKOOK	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	24/07/2024	Inspection Date	31/07/2024
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days