



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070428/Kqp3e2
16 RAFFLES QUAY	Date:	17/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 1144B	Veh. Inspected	SLM 7026U
Policy No.	D-24101904MFVS/12	Coverage	0
Claim No.	D24006463MFVS	Excess	\$0.00
Assign From	CAROLINE	Assign Date	26/07/2024

2. Vehicle Details

Make & Model	B.M.W. 523I (A)	C.C	2497
Engine No.	07677602N52B25AF	Year of Reg.	29/01/2011
Chassis No.	WBAFP32020C547027	Colour	METALLIC BLACK
Odometer	165310 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/55R17	PIRELLI	8
L/H Front Tyre	225/55R17	PIRELLI	8
R/H Rear Tyre	225/55R17	PIRELLI	8
L/H Rear Tyre	225/55R17	PIRELLI	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/07/2024	Inspection Date	29/07/2024
Survey held at	TROPICAL SUCCESS AUTO CARE BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535.		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days