



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 9980E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR DOOR RH	TO REPAIR SEE LABOUR	2,895.60	-
1	REAR DOOR INNER TRIM RH	NOT NECESSARY	1,682.30	-
1	REAR DOOR INNER LOCK RH	NOT NECESSARY	398.60	-
2	REAR DOOR HINGES RH @\$178.60	NOT NECESSARY	357.20	-
1	REAR DOOR WEATHERSTRIP RH	NOT NECESSARY	325.80	-
1	REAR DOOR CHROME	CUT	398.20	398.20
1	REAR SIDE SKIRT	TO REPAIR SEE LABOUR	1,455.70	-
1	REAR FENDER	TO REPAIR SEE LABOUR	3,215.80	-
1	REAR LOWER ARM RH	NOT NECESSARY	925.80	-
1	REAR TRAILING ARM RH	NOT NECESSARY	845.80	-
1	REAR ABSORBER RH	NOT NECESSARY	895.60	-
1	REAR KNUCKLE ARM RH	NOT NECESSARY	987.20	-
1	REAR WHEEL HUB BEARING RH	NOT NECESSARY	856.30	-
1	STABILIZER LINKAGE	NOT NECESSARY	348.90	-
	LESS 10% DISCOUNT		-1,558.88	-39.82
			14,029.92	358.38
1	REAR RIM RH (SN)	CUT	2,525.60	1,100.00
	LESS 10% DISCOUNT		-252.56	-
			2,273.04	1,100.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR FENDER INNER COWLING CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REAR FENDER INNER TRIM CLIPS (SN)	NOT NECESSARY	30.00	-
1	REAR TYRE (SN)	NOT NECESSARY	350.00	-
1	SET REAR DOOR INNER TRIM CLIPS (SN)	NOT NECESSARY	30.00	-
			440.00	-

Report Ref No. CS/INC24070432/Avh3e2(N)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS. INCLUSIVE OF THE REPAIR OF REAR DOOR RH, REAR SIDE SKIRT AND REAR FENDER.	NOT NECESSARY	2,000.00	-
	TO RESPRAY AFFECTED AREAS.		2,000.00	500.00
	TO TUFFCOAT AFFECTED AREA.	NOT NECESSARY	200.00	-
	TO REMOVE / REFIT INTERIOR UPHOLSTERY.	NOT NECESSARY	150.00	-
	TO APPLY SEALANT TO THE AFFECTED AREAS.	NOT NECESSARY	150.00	-
	TO PERFORM COMPUTERISED WHEEL ALIGNMENT.	NOT NECESSARY	160.00	-
	TO CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	150.00	-
	TO REMOVE / REPLACE REAR UNDERCARRIAGE.	NOT NECESSARY	200.00	-
	TO REMOVE / REFIT / REPLACE REAR DOOR MECHANISM.	NOT NECESSARY	160.00	-
			5,170.00	500.00
	<b>GRAND TOTAL</b>		<b>21,912.96</b>	<b>1,958.38</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>1,500.00</b>

Report Ref No. CS/INC24070432/Avh3e2(N)

TOTAL FOR SPARE PARTS: \$ 16,742.96 \$ 1,458.38

TOTAL FOR LABOUR : \$ 5,170.00 \$ 500.00

TOTAL REPAIR COST: \$ 21,912.96 \$ 1,958.38

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.