

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLR 5023P

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BOOT	TO REPAIR SEE LABOUR	\$1,130.00	\$0.00
1	REAR BOOT SPOILER	NOT NECESSARY	\$599.50	\$0.00
1	REAR BOOT WEATHER STRIP	NOT NECESSARY	\$389.50	\$0.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$490.00	\$0.00
2	REAR LAMP @\$425.00	NOT NECESSARY	\$850.00	\$0.00
2	REAR BOOT LAMP @\$395.00	NOT NECESSARY	\$790.00	\$0.00
2	REAR BUMPER SIDE RETAINER @\$135.00	NOT NECESSARY	\$270.00	\$0.00
1	SET REAR BUMPER PARKING SENSOR	SERVICEABLE	\$480.00	\$0.00
1	REAR BUMPER REINFORCEMENT	DENTED	\$499.00	\$499.00
1	REAR BUMPER LOWER LID	NOT FITTED	\$690.00	\$0.00
2	REAR BUMPER REFLACTOR @\$105.00	NOT NECESSARY	\$210.00	\$0.00
1	EXHAUST CHROME	NOT NECESSARY	\$499.00	\$0.00
2	REAR LOWER BRACKET @\$89.00	NOT NECESSARY	\$178.00	\$0.00
2	REAR NO.PLATE LAMP @\$105.00	NOT NECESSARY	\$210.00	\$0.00
1	REAR NO.PLATE & BOX	NOT NECESSARY	\$50.00	\$0.00
1	REAR PANEL GARNISH	NOT NECESSARY	\$395.80	\$0.00
1	REAR VIEW CAMERA	NOT NECESSARY	\$489.00	\$0.00
1	REAR BUMPER CENTRE BRACKET	DENTED	\$290.00	\$290.00
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$78.90)
			\$8,509.80	\$710.10

Special Nett					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
1	REAR BUMPER SPORT MODEL (SN)	DISTORTED / MTG BROKEN	\$1,280.00	\$800.00	
10	REAR BUMPER CLIPS @\$5.00 (SN)	NECESSARY	\$50.00	\$20.00	
			\$1,330.00	\$820.00	

Labour				
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
TO REMOVE & REFIT WIRING & CHECK WIRING		\$120.00	\$30.00	
TO KNOCKING, STRAIGHTENING REPAIR & RENEW ALL ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF REAR BOOT AND REAR END PANEL		\$1,000.00	\$700.00	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Labour				
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED DAMAGED AREA (2 COLORS)		\$1,000.00	\$700.00	
		\$2,120.00	\$1,430.00	
GRAND TOTAL		\$11,959.80	\$2,960.10	
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$2,300.00	
Report Ref No: CS/INC24070433/Dnh3				

TOTAL FOR SPARE PARTS: \$ 9,839.80 \$ 1,530.10
TOTAL FOR LABOUR: \$ 2,120.00 \$ 1,430.00
TOTAL REPAIR COST: \$ 11,959.80 \$ 2,960.10

ABT

ANG BRYAN TANI

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.