

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24070436/UUA3Q2**Date:** 06/01/2025REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0006820
Claimant Vehicle No : GBJ1687K **Insured Vehicle No :** PC7926C
 Date of Loss: 25/07/2024 Nature of Claim: TP Claim No: MFL2024D0009170

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ1687K**
 Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2837091
 Reg. Date: 16/01/2019 (Man. Year: 2018) Chassis No: JTFAT35Y70K212269
 Colour: Silver Odometer: 254439 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 155 R12 (D)
 Front Left Side: Arivo 6 mm Rear Left Side: VanTour 6/6 mm
 Front Right Side: Arivo 6 mm Rear Right Side: VanTour 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,285.70	3,816.45	3,469.25	47.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,810.00	1,070.00	2,740.00	71.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,095.70	4,886.45	6,209.25	55.96
Approved Total (Overridden) (S\$)		3,900.00		
(S\$)	11,095.70	3,900.00	7,195.70	64.85
+ GST 9.00/9.00% (S\$)	998.61	351.00	647.61	64.85
Nett Amount (S\$)	12,094.31	4,251.00	7,843.31	64.85
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		4,578.25		

INSPECTION

Date of Assignment: 31/07/2024
 Date Inspected: 31/07/2024 Inspected At: Kt Garage Pte Ltd (HQ)
 BLK 1 KAKI BUKIT AVENUE 6 #01-04, AUTO
 BAY@KAKI BUKIT ENTRANCE A
 Singapore 417883
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Sep 2024)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ1687K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	720.00 FL	*720.00 FL
2	1		*FRONT BUMPER INNER BRACKET (NPA)	No such part	0.00 FL	*- FL
3	1		*FRONT GRILLE	Not Necessary	710.00 FL	*- FL
4	1		*FRONT GRILLE EMBLEM	Not Necessary	105.00 FL	*- FL
5	1		*HEADLAMP RH	Cracked	1,158.00 FL	*1,158.00 FL
6	1		*RH HEADLAMP LOWER TRIM (NPA)	No such part	0.00 FL	*- FL
7	1		*RH CORNER PANEL	Cut / Cracked	495.00 FL	*489.00 FL
8	1		*RH CORNER PANEL CLIP	Not Necessary	5.50 FL	*- FL
9	1		*FRONT BODY PANEL ASSY	Not Necessary	1,451.50 FL	*- FL
10	1		*RH FRONT DOOR	Dented / Bent	2,681.60 FL	*2,681.60 FL
11	1		*RH FRONT DOOR CHECKER	Not Necessary	249.30 FL	*- FL
12	1		*RH FRONT DOOR OUTER WEATHERSTRIP MOULDING	Not Necessary	154.70 FL	*- FL
13	1		*RH FRONT DOOR WEATHERSTRIP	Not Necessary	278.00 FL	*- FL
14	1		*RH FRONT DOOR WEATHERSTRIP (NPA)	Not Necessary	0.00 FL	*- FL
15	1		*RH FRONT DOOR STEP GARNISH	Not Necessary	415.00 FL	*- FL
16	1		*WHEEL ARCH RUBBER SEAL	Not Necessary	64.00 FL	*- FL
17	1		*FRONT WINDSCREEN RUBBER	Not Necessary	505.00 FL	*- FL
18	1		*RH WINDSCREEN PILLAR	Repair	615.00 FL	*- FL
19	1		*COMPANY STICKER	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,687.60	5,078.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,401.90	1,262.15
Total Parts (\$\$)	7,285.70	3,816.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, KNOCK AND STRAIGHTEN DAMAGED PANEL AND RE-ALIGN THE SAME	New	1,680.00	500.00
2	TO RUST PROOF THE AFFECTED AREAS	New	120.00	30.00
3	TO CHECK ALL NECESSARY LIGHTING & WIRING	New	80.00	20.00
4	TO REMOVE FRONT DASHBOARD	New	400.00	0.00
5	TO REMOVE AND REFIT FRONT WINDSCREEN	New	180.00	0.00
6	TO PERFORM WATER SEEPAGE TEST	New	100.00	0.00
7	TO SPRAY PAINT THE AFFECTED AREAS	New	1,250.00	520.00
Gross Labour Cost (\$\$)			3,810.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >