

(08/11/13) - wef

ASS. REC. BY: Marcus

REF:

CD/111/24070436/Uu93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: G3J 1687K

at Workshop m/s LT Garage 11.30

of PC 7926C

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$ 60k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

* Date: _____ Person Contacted: LTA 12034

Vehicle: IN / OUT

Veh No: G3J 1687K Yr Regn: 16/10/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Car

Make: Toyota Dyno c.c. 2982

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 254439 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT35470K212269

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R 15

R: 155 R 12 van tour

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ARIVO

Front: 6 mm Rear: 6/6 mm

R/Bal. 6 mm L/Bal. 6/6 mm

L/Bal. 6 mm D.O.I. 31/07/24

D.O.A. 25/07/24

Survey held at _____

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

015 R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction dep 13h

12/8/24 fit bumper \$865.90, headlamp \$1759.80, door 2681.60
2/5 \$3900 in house AH 1c;

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

TOTAL



KT GARAGE PTE LTD UEN: 201906115R

Auto Bay@ Kaki Bukit Entrance A

BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

Date :

Not Authorised

TO: Whom it may concern

31/7/24

1/5 \$3900

3 days
Telephone

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-surveyed and is subject to approval from Insurance Company

Total Pages: 1

Our Customer : Zhe Kai Construction Pte Ltd

Vehicle No : GBJ1687K

Model : Toyota Dyna

Manufacture Year :

Date of Accident : 25/7/2024

Total Estimate Repair Days :

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front Bumper	1	\$720.00	\$720.00	Dis /
2	Front Bumper Inner Bracket	1			NS X
3	Front Grille	1	\$710.00	\$710.00	11 X
4	Front Grille Emblem	1	\$105.00	\$105.00	11 X
5	Headlamp - RH	1	\$1,158.00	\$1,158.00	CN /
6	RH Headlamp Lower Trim	1			MS X
7	RH Corner Panel 489	1	\$495.00	\$495.00	CN / CN /
8	RH Corner Panel Clip	1	\$5.50	\$5.50	11 X
9	Front Body Panel Assy	1	\$1,451.50	\$1,451.50	11 X
10	RH Front Door	1	\$2,681.60	\$2,681.60	Dis / Sent /
11	RH Front Door Checker	1	\$249.30	\$249.30	11 X
12	RH Front Door outer Weatherstrip Moulding	1	\$154.70	\$154.70	11 X
13	RH Front Door Weather strip	1	\$278.00	\$278.00	11 X
14	RH Front Door Weather Strip	1			11 X
15	RH Front Door Step Garnish	1	\$415.00	\$415.00	11 X
16	Wheel Arch Rubber Seal	1	\$64.00	\$64.00	11 X
17	Front Windscreen Rubber	1	\$505.00	\$505.00	11 X
18	RH Windscreen Pillar	1	\$615.00	\$615.00	11 X
	Sub Total			\$9,607.60	
	Less 25%			\$2,401.90	
	Sub Total 1			\$7,205.70	
B	Special Nett				
1	Company Sticker	1	\$80.00	\$80.00	Net 30 S/N
	Sub Total 2			\$80.00	
C	Labour				
1	To panel beat, knock and straighten damaged panel and re-align the same			\$1,680.00	500
2	To rust proof the affected areas			\$120.00	30
3	To check all necessary lighting & wiring			\$80.00	20
4	To remove front dashboard			\$400.00	11 X
5	To remove and refit front windscreen			\$180.00	11 X
6	To perform water seepage test			\$100.00	11 X
7	To spray paint the affected areas			\$1,250.00	520
	Total Labour			\$3,810.00	
	Total Repair Cost			\$11,095.70	