

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24070441/RPA3Q2**Date:** 15/11/2024**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MPC0001759_04
Claimant Vehicle No : SKX1210Y **Insured Vehicle No :** SJW3347R
Date of Loss: 19/07/2024 Nature of Claim: TP Claim No: MPC2024D0008840

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX1210Y**
Make & Model: PEUGEOT 3008, 1.2 EAT8 ACTIVE PREMIUM (A) Engine No: 10XVAY1768239
Reg. Date: 31/03/2021 (Man. Year: 2021) Chassis No: VF3MRHNSUMS038724
Colour: Blue Odometer: 95555 km
Engine Capacity: 1199 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,414.00	4,163.00	10,251.00	71.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,680.00	1,080.00	1,600.00	59.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,094.00	5,243.00	11,851.00	69.33
Approved Total (Overridden) (\$\$)		4,200.00		
(\$\$)	17,094.00	4,200.00	12,894.00	75.43
+ GST 9.00/9.00% (\$\$)	1,538.46	378.00	1,160.46	75.43
Nett Amount (\$\$)	18,632.46	4,578.00	14,054.46	75.43
+ Car Rental (2.0 x S\$100.00/day + 9.00% GST) (\$\$)		218.00		
+ Doc/Search Fee (\$\$)		2.18		
Nett Liability (\$\$)		4,798.18		

INSPECTION

Date of Assignment: 03/09/2024
Date Inspected: 03/09/2024 Inspected At: Mova Automotive Pte Ltd (Bukit Merah)
Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3
Singapore 159722
Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2024)
Parts:	M1-SUV	PEUGEOT 3008 1.2 EAT8 ACTIVE PREMIUM (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX1210Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,300.00 FL	*2,300.00 FL
2	1		*FRONT BUMPER UPPER GARNISH	Scratched	980.00 FL	*980.00 FL
3	1		*FRONT BUMPER UPPER GARNISH BRKT	Serviceable	490.00 FL	*- FL
4	1		*FRONT UPPER GRILLE BASE	Serviceable	830.00 FL	*- FL
5	1		*FRONT UPPER GRILLE BRACKET	Serviceable	840.00 FL	*- FL
6	1		*FRONT UPPER GARNISH EMBLEM 3008	Necessary	220.00 FL	*220.00 FL
7	1		*FRT UPPER GRILLE EMBLEM PEUGEOT	Not Necessary	220.00 FL	*- FL
8	1		*FRONT SPONGE	Serviceable	430.00 FL	*- FL
9	1		*FRONT LOWER GRILLE	Serviceable	680.00 FL	*- FL
10	1		*FRONT LOWER MOULDING	Scratched	990.00 FL	*990.00 FL
11	1		*FRONT LOWER SPOILER	Not Necessary	630.00 FL	*- FL
12	2		*HEADLAMP LH & RH	Serviceable	4,960.00 FL	*- FL
13	2		*HEADLAMP LOWER PANEL LH & RH	Serviceable	1,460.00 FL	*- FL
14	1		*FRONT PANEL SUPPORT BRACKET	Not Necessary	690.00 FL	*- FL
15	10		*FRONT BUMPER CLIPS	Necessary	80.00 FL	*80.00 FL
16	20		*FRONT BUMPER RIVETS	Not Necessary	160.00 FL	*- FL
17	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*50.00 FS
					Sub Total (S\$)	
					16,010.00	4,620.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	
					1,596.00	457.00
					Total Parts (S\$)	
					14,414.00	4,163.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT ,WELD PANEL BEAT ,STRAIGHTEN ,REPLACE DAMAGED PARTS & REALIGN AFFECTED AREAS	New	1,000.00	400.00
2	TO PUTTY SPRAY PAINT ON FRONT BUMPER TOP GARNISH ,FRONT BONNET ,FRONT BUMPER ,HEADLAMP LOWER PANEL LH & RH FRONT BUMPER LOWER GARNISH	New	1,200.00	450.00
3	TO CHECK WIRING & ELECTRICAL SYSTEM FOR PROPER FUNCTION	New	100.00	30.00
4	TO CONDUCT ADAS SYSTEM PROGRAMMING	New	380.00	200.00
Gross Labour Cost (\$\$)			2,680.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >