10/24/24, 8:55 AM Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24070445/EQP3E2

**Date:** 24/10/2024

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30003159610

Claimant Vehicle SMC7374D CRE6463C

No: SMG7274P Insured Vehicle No: GBF6463C

Date of Loss: 27/07/2024 Nature of Claim: TP Claim No: 368346

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMG7274P

 Make & Model:
 HONDA SHUTTLE HYBRID, 1.5 (A)
 Engine No:
 LEB7100694

 Reg. Date:
 28/12/2018 (Man. Year: 2018)
 Chassis No:
 GP72000433

 Colour:
 Red
 Odometer:
 413143 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: INTERTRAC 7 mm Rear Left Side: INTERTRAC 7 mm
Front Right Side: INTERTRAC 7 mm
Rear Right Side: INTERTRAC 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,331.57	2,446.50	2,885.07	54.11
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,490.00	1,020.00	470.00	31.54
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,821.57	3,466.50	3,355.07	49.18
	Approved Total (Overridden) (S\$)		2,750.00		
	Nett Amount (S\$)	6,821.57	2,750.00	4,071.57	59.69

**INSPECTION** 

Date of Assignment: 29/07/2024

Twin Wheel Auto Trading Enterprise (HQ)

Date Inspected: 31/07/2024 Inspected At: 38 Woodlands Road, #03-14 Woodlands Industrial Park

E1

Singapore 757700

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

10/24/24, 8:55 AM Adjuster Report

### **REPAIR DETAILS**

Reference

Part Source: (Last Synchronised: 24 Sep 2024)

Parts: N/A HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMG7274P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,099.80 FL	*1,099.80 FL
2	1		*REAR BOOT LID LOCK	Bent / Jammed	236.20 FL	*236.20 FL
3	1		*REAR BOOT LID EMBLEM	Not Necessary	60.60 FL	*- FL
4	1		*REAR BOOT LID HANDLE	Cracked	380.00 FL	*380.00 FL
5	2		*REAR BOOT LID LAMP	Not Necessary	1,100.80 FL	*- FL
6	1		*REAR BOOT LID W/S MOULDING	Cracked	260.00 FL	*120.00 FL
7	1		*REAR BUMPER	Broken	758.50 FL	*758.50 FL
8	2		*REAR LAMP	Not Necessary	1,080.40 FL	*- FL
9	1		*REAR BOOT LID HANDLE	Not Necessary	380.00 FL	*- FL
10	1		*RESERVE DOOR	Shorted	280.00 FS	*200.00 FS
11	1		*BOOT LID LOGO SHUTTLE	Necessary	55.90 FS	*55.90 FS
12	1		*BOOT LID LOGO HYBRID	Necessary	65.00 FS	*65.00 FS
13	1		*NUMBER PLATE	Not Necessary	30.00 FS	*- FS
14	1		*W/S SEALAND	Necessary	80.00 FS	*50.00 FS
F=Fra	ınchise	part. S=SpcNe	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	5,867.20	2,965.40
			- List Item Discoun	t on L Items 10.00/20.00% (S\$)	535.63	518.90
				Total Parts (S\$)	5,331.57	2,446.50
			Report was unsubmitt	ed during this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR TO SPRAY PAINT	New	750.00	500.00
2	LABOUR TO PANEL BEATING	New	600.00	400.00
3	TO DISMANTLE AND ASSEMBLE REAR W/S	New	140.00	120.00
		Gross Labour Cost (S\$)	1,490.00	1,020.00
	Report was up:	submitted during this print-out.		

< END OF ESTIMATES >