

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 18.06.2024

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
VEHICLE NO : **GBK298B**
MODEL : **TOYOTA HIACE**
DATE OF ACCIDENT : 10.10.2023
TIME OF ACCIDENT : 19:50 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 2,210.70	\$ 2,210.70
2	TAILGATE OUTER MOULDING <i>new</i>	1	\$ 364.90	\$ 364.90
3	TAILGATE LOGO <i>car</i>	1	\$ 70.50	\$ 70.50
4	TAILGATE 'HIACE' STICKER <i>new</i>	1	\$ 48.90	\$ 48.90
5	TAILGATE THIRD BRAKE LAMP <i>new</i>	1	\$ 185.90	\$ 185.90
6	TAILGATE WEATHERSTRIP <i>new</i>	1	\$ 397.80	\$ 397.80

TOTAL PRICE \$ 3,278.70
LESS 25% \$ 819.68
SUB TOTAL PRICE \$ 2,459.03

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
5	TAILGATE CENTER MOULDING CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
6	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
7	TAILGATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
8	TAILGATE STICKER '70KM/H' <i>3 new</i>	1	\$ 40.00	\$ 40.00
9	TAILGATE STICKER '8 PAX' <i>3 new</i>	1	\$ 40.00	\$ 40.00
9	TAILGATE WINDSCREEN SEALANT <i>3 new</i>	1	\$ 80.00	\$ 80.00
10	TAILGATE WINDSCREEN INNER SEAL <i>3 new</i>	1	\$ 60.00	\$ 60.00

TOTAL \$ 500.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBK298B**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 10.10.2023
 TIME OF ACCIDENT : 19:50 HOURS

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 1,000.00	200
2	SPRAY PAINTING TO AFFECTED AREA	\$ 800.00	200
3	WIRING, BULB CHECKING	\$ 80.00	x
4	TRANSFER TAILGATE MECHAISM	\$ 80.00	60
5	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x
6	REMOVE AND REFIX REVERSE CAMERA	\$ 120.00	50
7	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	✓
8	TO CHECK DIANOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 2,500.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 2,959.03
 TOTAL LABOUR COST : \$ 2,500.00
 TOTAL REPAIR COST : \$ 5,459.03

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian Lj
 19/06/24
 03 hrs

total: 2210.80

1750

630