

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070448/AUA3Q2**Date:** 14/05/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210156175
Claimant Vehicle No :	SLS5148H	Insured Vehicle No :	GBG1571B
Date of Loss:	24/07/2024	Nature of Claim:	TP
		Claim No:	1627451089SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS5148H		
Make & Model:	MERCEDES-BENZ C180, 1.8 SPORTS (A)	Engine No:	27091031251250
Reg. Date:	27/09/2017 (Man. Year: 2017)	Chassis No:	WDD1173422N496882
Colour:	Black	Odometer:	119994 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,556.30	11,339.30	23,217.00	67.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,520.00	2,210.00	5,310.00	70.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	42,076.30	13,549.30	28,527.00	67.80
Approved Total (Overridden) (S\$)		10,850.00		
(S\$)	42,076.30	10,850.00	31,226.30	74.21
+ GST 9.00/9.00% (S\$)	3,786.87	976.50	2,810.37	74.21
Nett Amount (S\$)	45,863.17	11,826.50	34,036.67	74.21
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
Nett Liability (S\$)		12,726.50		
Global Sum Settlement (S\$)		12,700.00		

INSPECTION

Date of Assignment:	25/07/2024	
Date Inspected:	25/07/2024 Inspected At:	JL Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit Singapore 415875
Estimated Period of Repair:	8.0 days	

Adjuster: ADRIAN LING**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*SIDE SKIRT	Not Necessary	2,972.00 FL	*- FL
2	1		*REAR DOOR RH	Dented	2,452.00 FL	*2,010.00 FL
3	1		*REAR DOOR CHROME MOULDING RH	Not Necessary	415.00 FL	*- FL
4	1		*REAR DOOR FRAME WEATHERSTIRP RH	Not Necessary	255.00 FL	*- FL
5	2		*REAR DOOR HINGE RH	Not Necessary	392.00 FL	*- FL
6	1		*REAR DOOR INNER LOCK RH	Damaged	805.00 FL	*549.00 FL
7	1		*REAR DOOR INNER TRIM RH	Cracked	1,723.00 FL	*1,180.00 FL
8	1		*REAR DOOR LOCK CATCHER RH	Not Necessary	70.00 FL	*- FL
9	1		*REAR DOOR WEATHERSTRIP RH	Necessary	409.00 FL	*310.00 FL
10	1		*REAR DOOR WATER SHIELD RH	Not Necessary	280.00 FL	*- FL
11	1		*REAR DOOR POWER WINDOW MOTOR RH	Not Necessary	745.00 FL	*- FL
12	1		*REAR DOOR REGULATOR RH	Damaged	884.00 FL	*695.00 FL
13	1		*REAR DOOR GLASS CHANNEL RH	Not Necessary	138.00 FL	*- FL
14	1		*REAR DOOR SPEAKER RH	Not Necessary	188.00 FL	*- FL
15	1		*REAR DOOR FRAME STEP GARNISH RH	Not Necessary	180.00 FL	*- FL
16	1		*REAR DOOR OUTER HANDLE RH	Damaged	631.00 FL	*391.00 FL
17	1		*REAR SEAT SIDE GARNISH RH	Not Necessary	122.00 FL	*- FL
18	1		*REAR FENDER RH	Dented	3,217.00 FL	*2,290.00 FL
19	2		*REAR FENDER COWLING	Not Necessary	486.00 FL	*- FL
20	1		*REAR WINDSCREEN GLASS C/W MOULDING	Necessary	1,308.00 FL	*1,308.00 FL
21	1		*REAR WHEEL SPORT RIM	Cut	1,890.00 FS	*800.00 FS
22	2		*REAR ABS SENSOR	Not Necessary	390.00 FL	*- FL
23	1		*REAR SHOCK ABSORBER	Not Necessary	670.00 FL	*- FL
24	1		*REAR LOWER ARM	Bent	540.00 FL	*540.00 FL
25	1		*REAR KNUCKLE ARM	Damaged	1,509.00 FL	*1,150.00 FL
26	1		*REAR WHEEL HUB WITH BEATING	Damaged	515.00 FL	*515.00 FL
27	1		*REAR UPPER ARM	Not Necessary	571.00 FL	*- FL
28	1		*REAR ADJUSTABLE ARM	Damaged	420.00 FL	*420.00 FL
29	1		*REAR CONTROL ARM	Damaged	219.00 FL	*219.00 FL
30	1		*REAR LINKAGE	Not Necessary	105.00 FL	*- FL
31	1		*REAR CROSSMEMBER	Not Necessary	3,648.00 FL	*- FL
32	1		*REAR BUMPER	Repair	2,008.00 FL	*- FL
33	2		*REAR BUMPER CORNER BRACKET	Not Necessary	374.00 FL	*- FL
34	2		*REAR BUMPER SIDE RETAINER	Not Necessary	254.00 FL	*- FL
35	1		*REAR BUMPER BRACKET (CENTER)	Not Necessary	345.00 FL	*- FL
36	1		*REVERSE SENSOR RH	Not Necessary	217.00 FL	*- FL
37	4		*REVERSE SENSOR HOLDER	Not Necessary	260.00 FL	*- FL
38	2		*TAILLAMP	Not Necessary	1,890.00 FL	*- FL
39	1		*SET SIDE SKIRT CLIP	Not Necessary	120.00 FS	*- FS
40	1		*SET REAR BUMPER CLIP	Not Necessary	80.00 FS	*- FS
41	1		*REAR DOOR SEALANT RH	Not Necessary	150.00 FS	*- FS
42	1		*SET REAR DOOR INNER TRIM CLIP RH	Necessary	50.00 FS	*30.00 FS
43	1		*SET REAR DOOR FRAME STEP GARNISH CLIP RH	Necessary	50.00 FS	*20.00 FS
44	1		*SET REAR SEAT SIDE GARNISH CLIP RH	Not Necessary	50.00 FS	*- FS
45	1		*REAR WINDSCREEN INNER SEAL	Necessary	80.00 FS	*40.00 FS
46	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*30.00 FS
47	1		*REAR WINDSCREEN GLASS SOLAR FILM	Not Necessary	650.00 FS	*- FS
48	1		*SET TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
49	4		*WHEEL TYRE	Not Necessary	2,720.00 FS	*- FS
50	1		*SET WHEEL CAP	Not Necessary	120.00 FS	*- FS
51	1		*BRAKE OIL	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	37,717.00	12,497.00
- List Item Discount on L Items 10.00/10.00% (\$)	3,160.70	1,157.70
Total Parts (\$)	34,556.30	11,339.30

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,800.00	700.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	600.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	650.00	30.00
5	FOUR WHEEL ALIGNMENT	New	180.00	80.00
6	REMOVE & REFIX AUDIO SPEAKER	New	120.00	0.00
7	TRANFER REAR DOOR MECHANISM	New	80.00	40.00
8	REMOVE & REINSTALL REAR WINDOW GLASS RH	New	80.00	40.00
9	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	60.00
10	REMOVE & REINSTALL & RESET REVERSE SENSOR	New	200.00	0.00
11	REMOVE & REFIX REAR WINDSCREEN	New	150.00	120.00
12	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
13	REMOVE AND REFIX REAR REVERSE SENSOR	New	80.00	0.00
14	RESET ABS LIGHT	New	600.00	0.00
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	850.00	180.00
16	TO REMOVE REAR UNDERCARRIAGE	New	380.00	220.00
17	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (\$\$)			7,520.00	2,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >