

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24070451/KPA3Q2
Date: 28/08/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0010240_01
Claimant Vehicle No : SLU9574Z Insured Vehicle No : YG5314D
Date of Loss: 29/07/2024 Nature of Claim: TP Claim No: MFL2024D0008546

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLU9574Z
Make & Model: TOYOTA COROLLA ALTIS, 1.6 Standard (A) Engine No: 1ZR0A46901
Reg. Date: 19/12/2017 (Man. Year: 2017) Chassis No: MR053REH604576235
Colour: Metallic Silver Odometer: 98875 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Toyo 8 mm Rear Left Side: Giti 9 mm
Front Right Side: Toyo 8 mm Rear Right Side: Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,326.57	2,326.57	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	1,100.00	450.00	29.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,876.57	3,426.57	450.00	11.61

INSPECTION

Date of Assignment: 30/07/2024
Date Inspected: 30/07/2024 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #04-01, Sin Ming AutoCity
Singapore 575722
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Aug 2024)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 Standard (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU9574Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	722.40 FL	*722.40 FL
2	1		*REAR BOOT LID	Bent	1,022.40 FL	*1,022.40 FL
3	1		*REAR BOOT LID TOYOTA LOGO EMBLEM	Necessary	76.90 FL	*76.90 FL
4	1		*REAR BOOT LID COROLLA EMBLEM	Necessary	52.30 FL	*52.30 FL
5	1		*REAR BOOT LID ALTIS EMBLEM	Necessary	56.90 FL	*56.90 FL
6	1		*REAR BOOT LID LAMP RH	Cracked	610.80 FL	*610.80 FL
7	1		*REAR TAILLAMP RH	Cut	555.90 FL	*555.90 FL
8	1		*REAR TAILLAMP CLIP RH	Necessary	4.50 FL	*4.50 FL
					Sub Total (\$\$)	3,102.10
					- List Item Discount on L Items 25.00/25.00% (\$\$)	775.53
					Total Parts (\$\$)	2,326.57

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK DENTS ON REAR END PANEL ,TAILLAMP PANEL RH ,REAR FENDER RH AND RENEW PARTS	New	550.00	500.00
2	TO SPRAY PAINT (INCLUDING BLEEDING ROOF PANEL SIDE RH)	New	1,000.00	600.00
Gross Labour Cost (\$\$)			1,550.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >