

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24070453/UPA3Q2**Date:** 14/10/2024REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002571
Claimant Vehicle No : SLA2744B **Insured Vehicle No :** SLQ3491P
 Date of Loss: 28/07/2024 Nature of Claim: TP Claim No: MFL2024D0009448

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA2744B**
 Make & Model: TOYOTA LEXUS, 2.5 ES300H CVT (A) Engine No: 2AR1433193
 Reg. Date: 26/02/2016 (Man. Year: 2015) Chassis No: JTHBW1GG202116822
 Colour: Silver Odometer: 2494 km
 Engine Capacity: 2494 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40Z R19 Rear Tyre Size: 245/40Z R19
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,167.04	4,625.37	6,541.67	58.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	1,400.00	630.00	31.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,197.04	6,025.37	7,171.67	54.34
Approved Total (Overridden) (S\$)		4,800.00		
(S\$)	13,197.04	4,800.00	8,397.04	63.63
+ GST 9.00/9.00% (S\$)	1,187.73	432.00	755.73	63.63
Nett Amount (S\$)	14,384.77	5,232.00	9,152.77	63.63
+ Car Rental (5.0 x S\$130.00/day) (S\$)		650.00		
+ Doc/Search Fee (S\$)		58.25		
Nett Liability (S\$)		5,940.25		

INSPECTION

Date of Assignment: 30/07/2024
 Date Inspected: 30/07/2024 Inspected At: LEE BROTHERS AUTOMOTIVE PTE. LTD. (HQ)
 1 Kaki Bukit Ave 6, #02-47 Autobay @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2024)
Parts:	143	TOYOTA LEXUS 2.5 ES300H CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA2744B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -RH	Dented / Bent	2,444.70 FN	*2,444.70 FN
2	1		*FRONT DOOR SIDE MIRROR	Not Necessary	1,055.90 FN	*- FN
3	1		*FRONT DOOR SIDE MIRROR COVER	Not Necessary	211.50 FN	*- FN
4	1		*FRONT DOOR GLASS OUTER MOULDING	Not Necessary	241.50 FN	*- FN
5	1		*FRONT DOOR GLASS FRAME MOULDING	Necessary	281.60 FN	*281.60 FN
6	1		*FRONT DOOR GLASS RUN CHANNEL	Not Necessary	310.50 FN	*- FN
7	1		*FRONT DOOR GLASS REGULATOR	Bent	561.90 FN	*561.90 FN
8	1		*FRONT DOOR INNER LOCK	Not Necessary	861.50 FN	*- FN
9	1		*FRONT DOOR INSULATION	Not Necessary	141.20 FN	*- FN
10	1		*FRONT DOOR W/STRIP	Not Necessary	221.60 FN	*- FN
11	1		*FRONT DOOR LOWER SEAL	Not Necessary	112.10 FN	*- FN
12	1		*FRONT DOOR CHECKER	Not Necessary	110.50 FN	*- FN
13	2		*FRONT DOOR HINGES	Bent / Twisted	221.00 FN	*221.00 FN
14	1		*FRONT FENDER -RH	Repair	1,468.50 FN	*- FN
15	1		*REAR DOOR RH	Repair	2,411.50 FN	*- FN
16	1		*REAR DOOR PROTECTOR STICKER	Necessary	180.20 FN	*180.20 FN
17	1		*SIDE SILL PANEL GARNISH	Cut / Torn	1,223.30 FN	*1,223.30 FN
18	1		*REAR DOOR EMBLEM HYBRID	Necessary	126.60 FN	*126.60 FN
19	1		*SET FRONT DOOR BLACK TAPE	Necessary	120.00 FS	*60.00 FS
20	1		*SET SIDE SILL PANEL GARNISH CLIP	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	12,385.60	5,129.30
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	1,218.56	503.93
Total Parts (\$\$)	11,167.04	4,625.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT WIRING	New	50.00	20.00
2	TO TUFF KOTE	New	100.00	30.00
3	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	New	1,080.00	850.00
4	TO PANEL BEAT ,CUT ,WELD REMOVE & REPLACE DAMAGED PARTS	New	800.00	500.00
Gross Labour Cost (\$\$)			2,030.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >