

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EG124060077/AVH3M4
Date: 26/08/2024

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : GBG1510C Insured Vehicle No : XE5021X
Date of Loss: 30/05/2024 Nature of Claim: TP Claim No: CDMCG24001357

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBG1510C
Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2684041
Reg. Date: 12/06/2017 (Man. Year: 2016) Chassis No: JTFAT35Y30K207537
Colour: White Odometer: 215534 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15C Rear Tyre Size: 155R12C
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,956.35	5,348.10	6,608.25	55.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,180.00	2,020.00	63.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,156.35	6,528.10	8,628.25	56.93
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	15,156.35	5,200.00	9,956.35	65.69

INSPECTION

Date of Assignment: 12/06/2024
Date Inspected: 21/06/2024 Inspected At: AUTOMOBILE HUB ENTERPRISE
1 KAKI BUKIT AVENUE 6
#01-15 AUTOBAY
SINGAPORE 417883
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Aug 2024)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG1510C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*TAILLAMP	Cut	510.80 FL	*510.80 FL
2	2		*TAILLAMP PANEL	Not Necessary	371.00 FL	*- FL
3	2		*REAR DOOR	Dented	4,000.00 FS	*3,000.00 FS
4	2		*REAR DOOR LOCK BAR	Bent	900.00 FS	*600.00 FS
5	2		*REAR DOOR LOCK BAR BRACKET (LOWER)	Not Necessary	300.00 FS	*- FS
6	2		*REAR DOOR LOCK BAR BRACKET (MIDDLE)	Not Necessary	200.00 FS	*- FS
7	2		*REAR DOOR LOCK BAR BRACKET (UPPER)	Not Necessary	300.00 FS	*- FS
8	2		*REAR DOOR LOCK HANDLE	Bent	400.00 FS	*300.00 FS
9	4		*REAR DOOR HINGE	Not Necessary	1,000.00 FS	*- FS
10	1		*REAR DOOR LOWER FRAME	Dented	800.00 FS	*500.00 FS
11	2		*REAR DOOR CORNER PILLAR	Not Necessary	2,000.00 FS	*- FS
12	1		*REAR BOX FLOOR PANEL TOP BOARD	Not Necessary	500.00 FS	*- FS
13	1		*REAR BOX ROOF PANEL METAL SHIELD	Dented	600.00 FS	*350.00 FS
14	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
15	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	12,176.80 5,475.80
					- List Item Discount on L Items 25.00/25.00% (\$\$)	220.45 127.70
					Total Parts (\$\$)	11,956.35 5,348.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	New	1,500.00	700.00
2	TO PUTTY, SPRAY PAINT, POLISH WAX	New	1,400.00	400.00
3	TO SPRAY TUFF COAT	New	150.00	0.00
4	WIRING, BULB CHECKING	New	50.00	30.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
Gross Labour Cost (\$\$)			3,200.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >