

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

TO	: 1ST CAPITAL Ergo
VEHICLE NO	: GBG1510C
VEHICLE MODEL	: TOYOTA DYNA
CHASSIS NO	: JTFAT35Y30K207537

LKK Auto Consultants hence notify
the Repairer of the following:

DATE: 24/6/2024

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date:

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILLAMP <i>ht</i>	2	\$ 255.40	\$ 510.80
2	TAILLAMP PANEL <i>New</i>	2	\$ 185.50	\$ 371.00
			TOTAL PRICE	\$ 881.80
			LESS 25%	\$ 220.45
			SUB TOTAL PRICE	\$ 661.35

SW.80
383.10

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR DOOR <i>Dented</i>	2	\$ 2,000.00	\$ 4,000.00
2	REAR DOOR LOCK BAR <i>Best</i>	2	\$ 450.00	\$ 900.00
3	REAR DOOR LOCK BAR BRACKET (LOWER) <i>2</i>	2	\$ 150.00	\$ 300.00
4	REAR DOOR LOCK BAR BRACKET (MIDDLE) <i>1 AP</i>	2	\$ 100.00	\$ 200.00
5	REAR DOOR LOCK BAR BRACKET (UPPER) <i>1 rear</i>	2	\$ 150.00	\$ 300.00
6	REAR DOOR LOCK HANDLE <i>Best</i>	2	\$ 200.00	\$ 400.00
7	REAR DOOR HINGE <i>new</i>	4	\$ 250.00	\$ 1,000.00
8	REAR DOOR LOWER FRAME <i>Dented</i>	1	\$ 800.00	\$ 800.00
9	REAR DOOR CORNER PILLAR <i>new</i>	2	\$ 1,000.00	\$ 2,000.00
10	REAR BOX FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 500.00	\$ 500.00
11	REAR BOX ROOF PANEL METAL SHIELD <i>Dented</i>	1	\$ 600.00	\$ 600.00
TOTAL			\$ 11,000.00	

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ 1,500.00	700
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,400.00	400
3	TO SPRAY TUFF COAT	\$ 150.00	x
4	WIRING, BULB CHECKING	\$ 50.00	30
8	TO REMOVE REVERSE SENSOR	\$ 100.00	50
TOTAL		\$ 3,200.00	

TOTAL PARTS COST	:	\$	11,661.35
TOTAL LABOUR COST	:	\$	3,200.00
TOTAL REPAIR COST	:	\$	14,861.35

total: 6528.10

L/S 15-2K

④ 4 Days