

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070458/AMA3Q2**Date:** 18/11/2024**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800044666		
Claimant Vehicle No :	SMF4983B	Insured Vehicle No :	SLZ1506Y		
Date of Loss:	30/07/2024	Nature of Claim:	TP	Claim No:	4082965091SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF4983B	Engine No:	L13B11031512
Make & Model:	HONDA JAZZ, 1.3 CVT (A)	Chassis No:	JHMGK3850JX227288
Reg. Date:	14/11/2018 (Man. Year: 2018)	Odometer:	39697 km
Colour:	White		
Engine Capacity:	1318 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65 R15	Rear Tyre Size:	175/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,052.96	4,777.36	4,275.60	47.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	2,430.00	950.00	28.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,432.96	7,207.36	5,225.60	42.03
Approved Total (Overridden) (S\$)		5,750.00		
(S\$)	12,432.96	5,750.00	6,682.96	53.75
+ GST 9.00/9.00% (S\$)	1,118.97	517.50	601.47	53.75
Nett Amount (S\$)	13,551.93	6,267.50	7,284.43	53.75
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		6,774.75		
Global Sum Settlement (S\$)		6,700.00		

INSPECTION

Date of Assignment:	30/07/2024	Chia Auto Services Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01 Vicom Inspection Center Singapore 415933
Date Inspected:	30/07/2024 Inspected At:	
Estimated Period of Repair:	7.0 days	

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Distorted	1,255.30 FL	*846.00 FL
2	1		*TAIL GATE LOGO	Necessary	80.00 FL	*45.00 FL
3	1		*TAIL GATE EMBLEM	Necessary	80.00 FL	*35.00 FL
4	1		*TAIL GATE LOCK	Damaged	260.00 FL	*260.00 FL
5	1		*TAIL GATE WEATHERSTRIP	Cut	155.00 FL	*155.00 FL
6	1		*TAIL GATE INNER TRIM	Cracked	290.00 FL	*290.00 FL
7	1		*TAIL GATE DETECTOR	Not Necessary	160.00 FL	*- FL
8	1		*TAIL GATE BUZZEL	Not Necessary	155.00 FL	*- FL
9	1		*TAIL GATE INNER HANDLE	Not Necessary	90.00 FL	*- FL
10	1		*TAIL GATE LAMP	N/S Cut	320.40 FL	*160.20 FL
11	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	160.20 FL	*160.20 FL
12	1		*NUMBER PLATE GARNISH	Cracked	230.00 FL	*230.00 FL
13	2		*NUMBER PLATE LAMP	Not Necessary	160.00 FL	*- FL
14	1		*REAR BUMPER	Distorted	620.00 FL	*545.00 FL
15	2		*REAR BUMPER SIDE RETAINER	Cracked	104.80 FL	*104.80 FL
16	1		*REAR BUMPER CENTRE GARNISH	Cracked	222.00 FL	*140.00 FL
17	2		*REAR BUMPER SIDE GARNISH	Cracked	300.00 FL	*210.00 FL
18	2		*TAILLAMP	Cracked	700.00 FL	*700.00 FL
19	1		*TAILLAMP PANEL	N/S Dented	380.00 FL	*190.00 FL
20	2		*REAR FENDER	Repair	1,780.00 FL	*- FL
21	1		*REAR FENDER INNER TRIM BOARD	N/S Cracked	841.00 FL	*295.00 FL
22	1		*REAR END PANEL	Dented	520.00 FL	*355.00 FL
23	1		*REAR END PANEL TOP GARNISH	Cracked	190.00 FL	*190.00 FL
24	1		*REAR FLOOR PANEL	Repair	890.00 FL	*- FL
25	1		*REAR FLOOR PANEL TOP BOARD	Deformed	240.00 FL	*240.00 FL
26	1		*REAR FLOOR PANEL TYRE SPONGE	Deformed	355.00 FL	*268.00 FL
27	1		*REAR NUMBER PLATE	Dented	50.00 FS	*50.00 FS
28	1		*TAILGATE WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
29	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	20.00 FS	*20.00 FS
30	1		*SET REAR BUMPER CLIPS	Necessary	22.00 FS	*22.00 FS
31	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	20.00 FS	*20.00 FS
32	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
33	1		*REAR END PANEL INSULATION SEALANT	Necessary	150.00 FS	*60.00 FS
34	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,160.70	5,861.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,107.74	1,083.84
Total Parts (\$\$)	9,052.96	4,777.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,200.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	1,000.00
3	TUFF COAT	New	200.00	60.00
4	WIRING CHECK	New	80.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	280.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	100.00	50.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	100.00	50.00
8	TRANSFER TAILGATE MECHANISM	New	100.00	60.00
9	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
Gross Labour Cost (\$\$)			3,380.00	2,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >