

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

SINGAPORE 048581

INV No. : SAC2400837
INV Date : 04-10-2024

Reference CD/FCI24070459/Rma3
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SCV 8331R
Insured Veh. SHD 6721Y
Claim No. D24006594MFCT
Policy No. D-24101861MFCT
Accident Date 26/07/2024
Inspection Date 31/07/2024

Description	Amount
Survey Inspection	300.00
Resurvey Inspection	0.00
Digital Photographs	0.00
Transportation	0.00
Sub-Total	300.00
GST (9%)	27.00
Grand Total	327.00

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CD/FCI24070459/Rma3 Date: 04/10/2024 Code: FCI2		
1. Policy Particulars :- DIRECT SETTLEMENT				
Insured Veh.	SHD 6721Y	Veh. Inspected	SCV 8331R	
Policy No.	D-24101861MFCT	Coverage	0	
Claim No.	D24006594MFCT	Excess	\$0.00	
Assign From	CHRIS LIM	Assign Date	30/07/2024	
2. Vehicle Details				
Make & Model	TOYOTA LEXUS ES300H 4DR SEDAN EXECUTIVE	C.C	2487	
Engine No.	A25A3A78999	Year of Reg.	30/06/2023	
Chassis No.	JTHB21B1802203431	Colour	BLACK	
Odometer	22192 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	FAIR	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	6	DUNLOP	6	
L/H Front Tyre	6	DUNLOP	6	
R/H Rear Tyre	6	DUNLOP	6	
L/H Rear Tyre	6	DUNLOP	6	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/07/2024	Inspection Date	31/07/2024	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SCV 8331R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	\$100.00	\$50.00
1	SEALANT (SN)	NOT NECESSARY	\$100.00	\$0.00
1	COVER ,RR BUMPER (SN)	DEFORMED	\$2,007.20	\$2,007.20
2	RETAINER ,ULTRASONIC (SN)	NECESSARY	\$110.20	\$110.20
2	RETAINER,ULTRASONIC (SN)	NECESSARY	\$110.20	\$110.20
2	TAPE MOULDING NO.1 (SN)	NECESSARY	\$122.20	\$122.20
17	PICEC ,RR BUMPER (SN)	NECESSARY	\$98.60	\$98.60
1	PAD ,RR BUMPER ,RH (SN)	NECESSARY	\$16.00	\$16.00
1	PAD ,RR BUMPER LH (SN)	NECESSARY	\$19.20	\$19.20
1	SUPPORT ,RR BUMPER (SN)	NOT NECESSARY	\$120.60	\$0.00
1	SUPPORT ,RR BUMPER (SN)	NOT NECESSARY	\$131.50	\$0.00
1	SUPPORT ,RR BUMPER (SN)	NOT NECESSARY	\$208.20	\$0.00
1	SUPPORT ,RR BUMPER (SN)	NOT NECESSARY	\$208.20	\$0.00
1	BRACKET ,RR BUMPER (SN)	NOT NECESSARY	\$6.90	\$0.00
1	BRACKET ,RR BUMPER (SN)	NOT NECESSARY	\$6.90	\$0.00
1	ABSORBER ,RR BUMPER (SN)	NOT NECESSARY	\$155.70	\$0.00
1	PROTECTOR ,RR (SN)	NOT NECESSARY	\$256.10	\$0.00
1	PROTECTOR ,RR (SN)	NOT NECESSARY	\$258.10	\$0.00
1	INSERT RR BUMPER (SN)	NOT NECESSARY	\$35.10	\$0.00
1	INSERT,RR BUMPER (SN)	NOT NECESSARY	\$35.10	\$0.00
1	REINFORCEMENT ,RR (SN)	NOT NECESSARY	\$1,142.30	\$0.00
1	BUMPER SUB-ASSY ,RR (SN)	CUT	\$939.40	\$939.40
1	RETAINER ,RR BUMPER (SN)	NOT NECESSARY	\$252.80	\$0.00
1	REFLECTOR ASSY (SN)	NOT NECESSARY	\$67.70	\$0.00
1	REFLECTOR ASSY (SN)	NOT NECESSARY	\$67.70	\$0.00
1	BRACKET ,KICK DOOR (SN)	NOT NECESSARY	\$199.10	\$0.00
1	SENSOR KICK DOOR (SN)	NOT NECESSARY	\$960.90	\$0.00
4	SENSOR ULTRASONIC (SN)	SERVICEABLE	\$2,521.60	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
4	CLIP ,ULTRASONIC (SN)	NECESSARY	\$66.40	\$66.40
			\$10,323.90	\$3,539.40
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND CONDUCT WATER LEAK TEST		\$240.00	\$240.00
	TO REMOVE AND REINSTALL REAR REVERSE SENSOR		\$240.00	\$240.00
	TO RESET ECU & REPROGRAMME		\$240.00	\$240.00
	LABOUR FOR LEXUS SURFACE CAREPER PANEL APPLICATION		\$128.00	\$128.00
	TO REPLACE AND REPAIR ON REAR ACCIDENT AFFECTED AR		\$1,920.00	\$960.00
	TO SPRAY PAINTIGN ON REAR ACCIDENT AFFECTED AREA		\$1,632.00	\$816.00
			\$4,400.00	\$2,624.00
GRAND TOTAL			\$14,723.90	\$6,163.40
	RECOMMENDED COST OF REPAIRS			\$6,163.40
Report Ref No: CD/FCI24070459/Rma3				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SCV 8331R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 2 of 12)

PHOTOGRAPHS FOR VEHICLE NO. : SCV 8331R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.

19-9607198-R

INSPECTION PHOTOS (Page 3 of 12)

PHOTOGRAPHS FOR VEHICLE NO. : SCV 8331R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 12)

PHOTOGRAPHS FOR VEHICLE NO. : SCV 8331R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 5 of 12)

PHOTOGRAPHS FOR VEHICLE NO. : SCV 8331R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933





TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.

19-9607198-R

INSPECTION PHOTOS (Page 6 of 12)

PHOTOGRAPHS FOR VEHICLE NO. : SCV 8331R









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 7 of 12)

PHOTOGRAPHS FOR VEHICLE NO. : SCV 8331R









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 8 of 12)

PHOTOGRAPHS FOR VEHICLE NO. : SCV 8331R









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 9 of 12)

PHOTOGRAPHS FOR VEHICLE NO. : SCV 8331R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 10 of 12)

PHOTOGRAPHS FOR VEHICLE NO. : SCV 8331R









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 11 of 12)

PHOTOGRAPHS FOR VEHICLE NO. : SCV 8331R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 12 of 12)

PHOTOGRAPHS FOR VEHICLE NO. : SCV 8331R



PHOTOGRAPHS FOR VEHICLE NO. : SCV 8331R

