

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070460/APA3Q2**Date:** 14/01/2025REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220112551
Claimant Vehicle No :	SMV2780Z	Insured Vehicle No :	SKN3030P
Date of Loss:	23/07/2024	Nature of Claim:	TP
		Claim No:	4890894208SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV2780Z	Engine No:	2ZR2H36024
Make & Model:	TOYOTA PRIUS, 1.8 PLUS (A)	Chassis No:	JTDZS3EUX0J060411
Reg. Date:	24/09/2020 (Man. Year: 2020)	Odometer:	130269 km
Colour:	Grey		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,345.00	865.00	480.00	35.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	1,030.00	1,250.00	54.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,625.00	1,895.00	1,730.00	47.72
+ GST 9.00/9.00% (S\$)	326.25	170.55	155.70	47.72
Nett Amount (S\$)	3,951.25	2,065.55	1,885.70	47.72
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		2,307.73		

INSPECTION

Date of Assignment:	26/07/2024		
Date Inspected:	26/07/2024	Inspected At:	1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01 Singapore 415933
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	380.00 FL	*380.00 FL
2	1		*FRT BUMPER BUMPER BRACKET	O/S Cracked	120.00 FL	*60.00 FL
3	1		*RHF FENDER	Deformed	480.00 FL	*480.00 FL
4	1		*RHF LED FOG LAMP	Cut	180.00 FL	*180.00 FL
5	1		*RH WING MIRROR	Repair	580.00 FL	*. FL
6	10		*FRT BUMPER CLIP	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,780.00	1,140.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	435.00	275.00
Total Parts (\$\$)	1,345.00	865.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,000.00	400.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA (FRT BUMPER)	New	1,200.00	600.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	80.00	30.00
Gross Labour Cost (\$\$)			2,280.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >