

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070461/DPA3Q2**Date:** 06/12/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7230081555
Claimant Vehicle No : SNF82R **Insured Vehicle No :** SNM1452M
Date of Loss: 25/07/2024 Nature of Claim: TP Claim No: 9657547036SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNF82R**
Make & Model: TOYOTA SUPRA RZ, 3.0 2DR COUPE (2WD) (A) Engine No: B58B30C0375888
Reg. Date: 22/01/2020 (Man. Year: 2019) Chassis No: WZ1DB42070W031843
Colour: White Odometer: 17142 km
Engine Capacity: 2998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 295/35 R18 Rear Tyre Size: 295/35 R18
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,570.40	12,633.85	17,936.55	58.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	890.00	1,110.00	55.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,570.40	13,523.85	19,046.55	58.48
Approved Total (Overridden) (S\$)		10,500.00		
Nett Amount (S\$)	32,570.40	10,500.00	22,070.40	67.76
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
Nett Liability (S\$)		10,900.00		

INSPECTION

Date of Assignment: 31/07/2024
Date Inspected: 31/07/2024 Inspected At: 11 VINYLs (HQ)
50 GAMBAS CRESCENT #09-17
PROXIMA@GAMBAS
Singapore 757022
Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	5,115.30 F	*3,638.00 FL
2	2		*FRONT BUMPER RETAINER	Not Necessary	760.00 F	*- FL
3	1		*FRONT BUMPER SIDE BRACKET	Not Necessary	210.00 F	*- FL
4	1		*FRONT BUMPER BEAM	Not Necessary	659.80 F	*- FL
5	1		*FRONT BUMPER SPONGE	Not Necessary	399.30 F	*- FL
6	1		*FRONT BUMPER RH AIR GARNISH	Not Necessary	210.00 F	*- FL
7	1		*FRONT BUMPER RH LOWER GRILLE	Not Necessary	345.00 F	*- FL
8	10		*FRONT BUMPER CLIPS	Necessary	70.00 FS	*20.00 FS
9	2		*FRONT BUMPER LOWER LID SPOILER (UPPER)	Cut / Distorted (1 PCS ONLY)	2,198.00 F	*1,099.00 FL
10	10		*FRONT BUMPER LOWER LID CLIPS	Not Necessary	80.00 F	*- FL
11	1		*FRONT LOGO	Necessary	210.00 F	*210.00 FL
12	1		*FRONT FENDER DUST COVER	Not Necessary	305.00 F	*- FL
13	10		*FRONT FENDER DUST COVER CLIPS	Not Necessary	60.00 F	*- FL
14	2		*FRONT PARKING SENSOR	Damaged	3,304.00 F	*542.70 FL
15	4		*FRONT PARKING SENSOR HOLDER	Necessary	160.00 F	*160.00 FL
16	4		*FRONT PARKING SENSOR RING	Necessary	120.00 F	*120.00 FL
17	1		*RH HEAD LAMP ASSEMBLY	Mtg Broken	11,305.00 F	*8,102.10 FL
18	1		*RH HEAD LAMP HOLDER	Broken	310.00 F	*310.00 FL
19	1		*RH FRONT SPORT RIM	Cut / Dented	1,990.00 FS	*500.00 FS
20	1		*RH FRONT TYRE	Not Necessary	699.00 F	*- FL
21	1		*TPMS SENSOR	Cut	390.00 F	*390.00 FL
22	1		*RADIATOR COOLER	Bent / Dented	1,580.00 F	*1,580.00 FL
23	1		*COOLANT	Serviceable	90.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	30,570.40	16,671.80
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	4,037.95
Total Parts (\$\$)	30,570.40	12,633.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT ALL WIRES, CHECK WIRES	New	100.00	30.00
2	TO REMOVE & R RENEW SPORT RIM & TYRE W/BALANCING	New	100.00	60.00
3	TO KNOCK ,STRAIGHTEN REPAIR & RENEW ALL ACCIDENT AFFECTED AREAS	New	1,000.00	500.00
4	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED DAMAGED AREA	New	800.00	300.00
Gross Labour Cost (\$\$)			2,000.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >