

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24070462/UUA3Q2**Date:** 18/10/2024**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D24MFL0004280
Claimant Vehicle No : SKW8666A **Insured Vehicle No :** PA1997Y
 Date of Loss: 26/07/2024 Nature of Claim: TP Claim No: MFL2024D0008817

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW8666A**
 Make & Model: HONDA FIT, 1.3 GF CVT (A) Engine No: L13B1437285
 Reg. Date: 12/03/2019 (Man. Year: 2018) Chassis No: GK31331080
 Colour: Grey Odometer: 52155 km
 Engine Capacity: 1317 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,593.64	1,210.72	2,382.92	66.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,180.00	900.00	280.00	23.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,773.64	2,110.72	2,662.92	55.78
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	4,773.64	1,650.00	3,123.64	65.44
+ GST 9.00/9.00% (S\$)	429.63	148.50	281.13	65.44
Nett Amount (S\$)	5,203.27	1,798.50	3,404.77	65.44
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		2,125.75		

INSPECTION

Date of Assignment: 21/08/2024
 Date Inspected: 21/08/2024 Inspected At: Progressive Car Care Pte Ltd (HQ)
 Estimated Period of Repair: 3.0 days Blk 3022A Ubi Road 1, #01-45/46
 Singapore 408716

Adjuster: MARCUS CHUA**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2024)
Parts:	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW8666A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	657.70 FL	*657.70 FL
2	2		*FRONT BUMPER SIDE RETAINER -LH/RH	Not Necessary	30.80 FL	*- FL
3	10		*FRONT BUMPER CLIPS	Not Necessary	39.00 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	258.00 FL	*- FL
5	1		*FRONT BUMPER CENTER LOWER GRILLE	Not Necessary	180.70 FL	*- FL
6	1		*FRONT BUMPER TOW COVER	Not Necessary	18.70 FL	*- FL
7	1		*FRONT GRILLE BASE	Cracked	268.80 FL	*268.80 FL
8	1		*FRONT GRILLE LOWER CHROME	Not Necessary	202.80 FL	*- FL
9	1		*FRONT GRILLE OUTER GARNISH WITH CHROME	Not Necessary	224.10 FL	*- FL
10	1		*FRONT GRILLE LOGO	Not Necessary	30.00 FL	*- FL
11	1		*FRONT GRILLE TOP GARNISH	Not Necessary	24.20 FL	*- FL
12	5		*FRONT GRILLE TOP GARNISH CLIPS	Not Necessary	19.50 FL	*- FL
13	2		*FRONT GRILLE LOGO CLIPS	Not Necessary	13.60 FL	*- FL
14	2		*HEADLAMP UNIT -LH/RH	Not Necessary	1,590.00 FL	*- FL
15	2		*HEADLAMP LOWER RETAINER -LH/RH	Not Necessary	66.80 FL	*- FL
16	1		*BONNET	Dented / Buckled	586.90 FL	*586.90 FL
17	6		*BONNET INSULATOR CLIPS	Not Necessary	23.40 FL	*- FL
18	1		*BONNET LOCK	Serviceable	111.60 FL	*- FL
19	2		*BONNET RUBBER (INNER) -LH/RH	Not Necessary	44.60 FL	*- FL
20	1		*BONNET RUBBER (OUTER) -LH/RH	Not Necessary	44.60 FL	*- FL
21	1		*FRONT NUMBER PLATE WITH CASING	Serviceable	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,480.80	1,513.40
- List Item Discount on L Items 20.00/20.00% (S\$)	887.16	302.68
Total Parts (S\$)	3,593.64	1,210.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS ,REMOVE ,REPLACE ACCIDENT PORTIONS	New	550.00	380.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	600.00	500.00
3	TO CHECK WIRING	New	30.00	20.00
Gross Labour Cost (\$\$)			1,180.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >