8/13/24, 1:15 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24070463/UNH3M4

Date: 13/08/2024

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001271862

Claimant Vehicle YP6093L Insured Vehicle No: YL8589G

Date of Loss: 06/03/2024 Nature of Claim: TP Claim No: 350805

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YP6093L

 Make & Model:
 MITSUBISHI FEB21CR4SDEB, 3.0 D (M)
 Engine No:
 4P10C32904

 Reg. Date:
 13/04/2017 (Man. Year: 2016)
 Chassis No:
 FEB21CA20077

 Colour:
 White
 Odometer:
 266140 km

Engine Capacity: 2998 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15 (D)
Front Left Side: Austone 7 mm Rear Left Side: Austone 7/7 mm
Front Right Side: Austone 7 mm Rear Right Side: Austone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,000.00	0.00	1,000.00	100.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		650.00	400.00	250.00	38.46
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	1,650.00	400.00	1,250.00	75.76

INSPECTION

Date of Assignment: 30/07/2024

LIU'S BROTHER AUTO ENGINEERING

WORKSHOP (HQ)

Date Inspected: 30/07/2024 Inspected At: BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @

KAKI BUKIT

SINGAPORE 417883

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 13 Aug 2024)

Parts: N/A MITSUBISHI FEB21CR4SDEB 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YP6093L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH CARGO FRIDGE BOX DOOR WEATHERSTRIP	Serviceable	650.00 FS	*- FS
2	1		*REAR LH CARGO FRIDGE BOX DOOR HINGE	Repair	350.00 FS	*-FS
F=Fra	anchise	part. S=Spcl	Nett.	,		
				Total Parts (S\$)	1,000.00	0.00
				1		
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	400.00	200.00
2	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	250.00	200.00
	Gross Labour Cost (S\$)		650.00	400.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >