



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRE SINGAPORE 239924		Ref: Date: Code:	CS/AGI24070467/Kvp3m4 23/08/2024 AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SME 7423L	Veh. Inspected	SNN 8660C	
Policy No.	P10440557R03	Coverage	0	
Claim No.	C10030786/JK	Excess	\$0.00	
Assign From	JANICE KOH	Assign Date	29/07/2024	
2. Vehicle Details				
Make & Model	TOYOTA SIENTA HYBRID 1.5X CVT	C.C	1490	
Engine No.	M15AY790431	Year of Reg.	28/12/2023	
Chassis No.	MXPL101084080	Colour	METALLIC BEIGE	
Odometer	6187 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	185/65R15	TOYO	9	
L/H Front Tyre	185/65R15	TOYO	9	
R/H Rear Tyre	185/65R15	TOYO	9	
L/H Rear Tyre	185/65R15	TOYO	9	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/07/2024	Inspection Date	29/07/2024	
Survey held at	RC AUTO 160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				