



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070471/Kvp3m4
16 RAFFLES QUAY	Date:	23/08/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 9354C	Veh. Inspected	SMD 8948M
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24006574MFCT	Excess	\$0.00
Assign From	CAROLINE	Assign Date	29/07/2024

2. Vehicle Details

Make & Model	HONDA ODYSSEY 2.4 EXV-S CVT SR	C.C	2356
Engine No.	K24W72401586	Year of Reg.	10/09/2018
Chassis No.	JHMRC1890JC203048	Colour	METALLIC SILVER
Odometer	114410 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/55R17	MICHELIN	8
L/H Front Tyre	215/55R17	MICHELIN	8
R/H Rear Tyre	215/55R17	MICHELIN	8
L/H Rear Tyre	215/55R17	MICHELIN	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/07/2024	Inspection Date	05/08/2024
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days