

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24070473/KNP3M4**Date:** 14/08/2024REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SHC5301M **Insured Vehicle No :** GBH9087A

Date of Loss: 28/07/2024 Nature of Claim: TP Claim No: DMCV2400152H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5301M**

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2G75519

Reg. Date: 14/07/2020 (Man. Year: 2020) Chassis No: JTDKB3FU903091198

Colour: Metallic Pearl White/Red Odometer: 294444 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: Wanli 6 mm Rear Left Side: Grenlander 9 mm

Front Right Side: Wanli 6 mm Rear Right Side: Grenlander 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,988.15	3,290.49	4,697.66	58.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,990.00	710.00	4,280.00	85.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,978.15	4,000.49	8,977.66	69.18
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	12,978.15	3,200.00	9,778.15	75.34
+ GST 9.00/9.00% (S\$)	1,168.03	288.00	880.03	75.34
Nett Amount (S\$)	14,146.18	3,488.00	10,658.18	75.34

INSPECTION

Date of Assignment: 30/07/2024

Date Inspected: 31/07/2024 Inspected At:

TRANS-CAB AUTO SERVICES PTE LTD
NO.2 ANG MO KIO STREET 63
SINGAPORE 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Aug 2024)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5301M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER,FRONT BUMPER	Buckled / Dented	653.31 FL	*653.31 FL
2	1		*ABSORBER,FRONT BUMPER ENERGY	Serviceable	100.91 FL	*- FL
3	1		*REINFORCEMENT SUB-ASSY,FRONT BUMPER	Repair	902.16 FL	*- FL
4	1		*SUPPORT,FRONT BUMPER SIDE,RH	Distorted	100.49 FL	*100.49 FL
5	1		*MOULDING,FRONT BUMPER SIDE,RH	Cut	120.86 FL	*120.86 FL
6	1		*COVER,FRONT BUMPER HOLE,RH	Missing	38.22 FL	*38.22 FL
7	1		*GRILLE SUB-ASSY,RADIATOR	Serviceable	532.88 FL	*- FL
8	1		*GRILLE RADIATOR LOWER NO,1	Serviceable	224.70 FL	*- FL
9	1		*JAR ASSY,WINDSHIELD WASHER	Serviceable	276.15 FL	*- FL
10	1		*WHEEL DISC	Serviceable	2,554.70 FL	*- FL
11	1		*FENDER SUB-ASSY,FRONT RH	Repair	1,236.69 FL	*- FL
12	1		*LINER,FRONT FENDER,RH	Serviceable	255.36 FL	*- FL
13	1		*EMBLEM,SIDE PANEL,RH	Necessary	68.88 FL	*68.88 FL
14	1		*UNIT ASSY,HEADLAMP,RH	Mtg Cracked	3,325.56 FL	*3,325.56 FL
15	1		*FRT BUMPER CLIP	Necessary	65.00 FS	*60.00 FS
16	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
17	1		*FRT BUMPER SIDE RETAINER CLIP	Not Necessary	65.00 FS	*- FS
Sub Total (\$\$)						10,585.87 4,367.32
- List Item Discount on L Items 25.00/25.00% (\$\$)						2,597.72 1,076.83
Total Parts (\$\$)						7,988.15 3,290.49

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	440.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
5	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,000.00	250.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF REAR FENDER PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			4,990.00	710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >