

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24070474/KPA3Q2

Date: 17/11/2025

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0000326_04
Claimant Vehicle No :	SHC5262S	Insured Vehicle No :	SKZ9419A
Date of Loss:	25/07/2024	Nature of Claim:	TP
		Claim No:	MFL2024D0008816

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5262S	Engine No:	2ZR2G75279
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU103091177
Reg. Date:	30/06/2020 (Man. Year: 2020)	Odometer:	334523 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Wanli 9 mm	Rear Left Side:	Grenlander 6 mm
Front Right Side:	Wanli 9 mm	Rear Right Side:	Grenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,514.11	873.65	4,640.46	84.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,250.00	470.00	4,780.00	91.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,764.11	1,343.65	9,420.46	87.52
Approved Total (Overridden) (S\$)		1,050.00		
(S\$)	10,764.11	1,050.00	9,714.11	90.25
+ GST 9.00/9.00% (S\$)	968.77	94.50	874.27	90.25
Nett Amount (S\$)	11,732.88	1,144.50	10,588.38	90.25
+ Car Rental (4.0 x S\$97.01/day) (S\$)		388.04		
+ Loss of Earnings (4.0 x S\$40.00/day) (S\$)		160.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		1,719.79		

INSPECTION

Date of Assignment:	31/07/2024		
Date Inspected:	31/07/2024	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

We have checked and confirmed that all part prices are correct. The actual work carried out and listed as labour and spray painting is accurate, and the fees charged for labour and spray painting are correct.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Mar 2025)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5262S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER REAR BUMPER	Bent	612.68 FL	*612.68 FL
2	1		*GUARD ,REAR BUMPER CENTER	Cut	472.19 FL	*472.19 FL
3	1		*REFLECTOR ASSY ,REFLEX RH	Serviceable	49.25 FL	*- FL
4	1		*SEAL REAR BUMPER SIDE RH	Serviceable	149.21 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	167.48 FL	*- FL
6	1		*PANEL SUB-ASSY ,QUARTER RH	Repair	1,099.46 FL	*- FL
7	1		*LINER REAR WHEEL HOUSE RH	Serviceable	176.09 FL	*- FL
8	1		*COVER FLOOR UNDER RH	Serviceable	220.50 FL	*- FL
9	1		*COVER FLOOR UNDER LH	Serviceable	304.92 FL	*- FL
10	1		*COVER REAR FLOOR	Serviceable	290.43 FL	*- FL
11	1		*COVER DECK TRIM REAR	Serviceable	159.39 FL	*- FL
12	1		*PANEL SUB-ASSY BODY LOWER BACK	Repair	824.46 FL	*- FL
13	1		*LENS & BODY REAR COMBINATION LAMP RH	Serviceable	428.19 FL	*- FL
14	1		*LENS & BODY REAR COMBINATION LAMP NO.2 RH	Serviceable	329.49 FL	*- FL
15	1		*COVER REAR COMBINATION LAMP RH	Serviceable	88.41 FL	*- FL
16	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
17	1		*REAR BUMPER CLIP	Necessary	65.00 FS	*60.00 FS
18	1		*END PANEL INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
19	1		*REAR BUMPER PROTECTOR	No such part	180.00 FS	*- FS
20	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
21	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS
22	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,857.15	1,144.87
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,343.04	271.22
Total Parts (\$\$)	5,514.11	873.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	600.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	220.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,000.00	200.00
4	TO TRANSFER OF TAILGATE FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
5	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
7	TO TRANSFER OF TAILGATE FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
8	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			5,250.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >