

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24070476/AQP3E2
Date: 24/10/2024REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SNQ2186D **Insured Vehicle No :** SMG2169T

Date of Loss: 28/07/2024 Nature of Claim: TP Claim No: DMPU2400032H/02/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNQ2186D**

Make & Model: NISSAN QASHQAI, 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R (A) Engine No: MR20412874W

Reg. Date: 17/06/2016 (Man. Year: 2016) Chassis No: SJNFBAJ11U1687298

Colour: Grey Odometer: 124707 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R19 Rear Tyre Size: 225/45 R19

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,763.30	3,279.13	4,484.17	57.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,840.00	1,400.00	2,440.00	63.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,603.30	4,679.13	6,924.17	59.67
Approved Total (Overridden) (S\$)		3,750.00		
(S\$)	11,603.30	3,750.00	7,853.30	67.68
+ GST 9.00/9.00% (S\$)	1,044.30	337.50	706.80	67.68
Nett Amount (S\$)	12,647.60	4,087.50	8,560.10	67.68

INSPECTION

Date of Assignment: 30/07/2024

Date Inspected: 30/07/2024 Inspected At: HD Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Oct 2024)
Parts:	M1-SUV	NISSAN QASHQAI 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNQ2186D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	788.70 FL	*788.70 FL
2	1		*REAR BUMPER REFLECTOR	N/S Cracked	119.00 FL	*59.50 FL
3	1		*REAR BUMPER TOWING COVER	Not Necessary	28.50 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER (FRONT)	Not Necessary	79.00 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Dented	691.50 FL	*619.00 FL
6	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	570.60 FL	*- FL
7	4		*REAR BUMPER LOWER BRACKET	Not Necessary	198.00 FL	*- FL
8	1		*REAR BUMPER SPONGE	Cracked	173.80 FL	*173.80 FL
9	2		*REAR FENDER INNER COWLING	Not Necessary	415.80 FL	*- FL
10	1		*REAR FENDER ARCED GARNISH	O/S Cracked	1,062.60 FL	*531.30 FL
11	2		*TAIL LAMP	Not Necessary	1,057.00 FL	*- FL
12	1		*TAILGATE LOGO	Not Necessary	52.50 FL	*- FL
13	1		*TAILGATE EMBLEM QASHQAI	Necessary	80.90 FL	*80.90 FL
14	1		*TAILGATE LOCK DETECTOR	Not Necessary	396.40 FL	*- FL
15	1		*TAILGATE INNER LOCK	Not Necessary	172.80 FL	*- FL
16	1		*TAILGATE WEATHER STRIP	Cut	222.40 FL	*222.40 FL
17	1		*REAR END PANEL	Dented	570.60 FL	*570.60 FL
18	1		*REAR END PANEL TOP GARNISH	Deformed	119.50 FL	*119.50 FL
19	2		*REAR TOOLS SPONGE COMPARTMENT	Not Necessary	737.40 FL	*- FL
20	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
21	1		*SET TAILLAMP CLIP	Not Necessary	30.00 FS	*- FS
22	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
23	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
24	1		*SET REAR WHEEL ARCH CLIP	Necessary	50.00 FS	*20.00 FS
25	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
26	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
27	4		*REVERSE SENSOR	Damaged	480.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,517.00	3,595.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	753.70	316.57
Total Parts (\$\$)	7,763.30	3,279.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	New	1,800.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	600.00
3	TUFF COAT	New	250.00	60.00
4	WIRING AND BULB CHECK	New	80.00	30.00
5	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	New	250.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			3,840.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >