

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBE 7555U

REPLACEMENT OF PARTS							
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)			
1	REAR BUMPER	GRAZED	\$622.10	\$622.10			
1	REAR LH FENDER LH (BODY PANEL)	BADLY DENTED	\$1,849.70	\$1,849.70			
1	REAR LH WHEEL HUB-CAB	CUT	\$278.00	\$220.00			
1	REAR LH SLIDING DOOR	BADLY DENTED	\$1,682.40	\$1,682.40			
	LESS 0.00 / 25.00% DISCOUNT		\$0.00	(\$1,093.55)			
			\$4,432.20	\$3,280.65			

Special Nett							
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)			
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	\$65.00	\$0.00			
1	REAR LH "CORPORATE" ADVERTISEMENT & ARTWORK (SN)	NECESSARY	\$280.00	\$150.00			
			\$345.00	\$150.00			

Labour				
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS		\$900.00	\$600.00	
TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS		\$700.00	\$600.00	
TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA		\$60.00	\$50.00	
•		\$1,660.00	\$1,250.00	
GRAND TOTAL		\$6,437.20	\$4,680.65	
RECOMMENDED COST OF LUMP SUM REPAIRS			\$3,700,00	

MARKET VALUE: \$23,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$7,612.00=NETT VALUE: \$15,388.00

Report Ref No: CS/FCI24070482/Uqh3

\$3,700.00

CKS

MARCUS CHUA KANG SENG

(TO ITS PRE-ACCIDENT CONDITION)

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.