



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070482/Uqh3
16 RAFFLES QUAY	Date:	21/08/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 7163A	Veh. Inspected	GBE 7555U
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24006097MFCT	Excess	\$0.00
Assign From	JOANNE TAN	Assign Date	30/07/2024

2. Vehicle Details

Make & Model	TOYOTA HIACE (M)	C.C	2982
Engine No.	1KD2596927	Year of Reg.	21/03/2016
Chassis No.	JTFHT02P500191796	Colour	WHITE
Odometer	161820 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15	AUSTONE	6
L/H Front Tyre	195R15	AUSTONE	6
R/H Rear Tyre	195R15	AUSTONE	6
L/H Rear Tyre	195R15	AUSTONE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/07/2024	Inspection Date	30/07/2024
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days