

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

SINGAPORE 048581

INV No. : SAC2401477

INV Date : 20-11-2024

Reference CD/FCI24070485/Rma3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SNK 5491J
Insured Veh. SHC 3479Y
Claim No. D24006542MFCT/CTPL/TPD 2
Policy No. D-24101861MFCT
Accident Date 26/07/2024
Inspection Date 02/08/2024

Description	Amount
Third Party Express Settlement	450.00
Sub-Total	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref:	CD/FCI24070485/Rma3q2	
		Date:	20/11/2024	
		Code:	FCI2	
1. Policy Particulars :- DIRECT SETTLEMENT				
Insured Veh.	SHC 3479Y	Veh. Inspected	SNK 5491J	
Policy No.	D-24101861MFCT	Coverage	0	
Claim No.	D24006542MFCT/CTPL/TPD 2	Excess	\$0.00	
Assign From	-	Assign Date	30/07/2024	
2. Vehicle Details				
Make & Model	KIA SORENTO HYBRID 1.6A SX TECH PACK SR	C.C	1598	
Engine No.	G4FTNH044348	Year of Reg.	25/04/2023	
Chassis No.	KNARH81GMP5142821	Colour	BLACK	
Odometer	34662 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	FAIR	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	235/65 R17	CONTINENTAL	6	
L/H Front Tyre	235/65 R17	CONTINENTAL	6	
R/H Rear Tyre	235/65 R17	CONTINENTAL	6	
L/H Rear Tyre	235/65 R17	CONTINENTAL	6	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/07/2024	Inspection Date	02/08/2024	
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNK 5491J

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	PNL SEALANT (SN)	NECESSARY	\$100.00	\$80.00
1	SUNDRIES (SN)	NECESSARY	\$100.00	\$20.00
1	COVER -FR BUMPER UPR (SN)	SCRATCHED	\$661.00	\$661.00
1	MOULDING FRONT BUMPER RH (SN)	SCRATCHED	\$69.00	\$69.00
1	GARNISH ASSY -FNDR SIDE RH (SN)	SCRATCHED	\$76.00	\$76.00
1	GARNISH ASSY-FR DR SIDE RH (SN)	NOT NECESSARY	\$196.00	\$0.00
1	GARNISH ASSY-RR DR SIDE ,RH (SN)	NOT NECESSARY	\$210.00	\$0.00
1	GRILLE FRONT BUMPER (SN)	SCRATCHED	\$319.00	\$319.00
1	PANEL ASSY FRONT DOOR RH (SN)	TO REPAIR SEE LABOUR	\$1,411.00	\$0.00
1	PANEL ASSY FENDER RH (SN)	TO REPAIR SEE LABOUR	\$772.00	\$0.00
1	GARNISH ASSY DR FRAME RH (SN)	NOT NECESSARY	\$48.00	\$0.00
1	MOULDING ASSY FRT DR FRAME RH (SN)	NOT NECESSARY	\$46.00	\$0.00
1	WHEEL ASSY ALUMINIUM (SN)	SCRATCHED	\$900.00	\$900.00
1	VALVE-TPMS (SN)	NECESSARY	\$159.00	\$159.00
1	ARM COMPLETE FR LWR, RH (SN) (ADDITIONAL)	BENT	\$474.00	\$474.00
30	CLIP SIDE SILL MOULDING MTG (SN) (ADDITIONAL)	NECESSARY	\$60.00	\$60.00
			\$5,601.00	\$2,818.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	RENEW RHS LOWER ARM FRONT (ADDITIONAL)		\$260.00	\$260.00
	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT		\$120.00	\$120.00
	RENEW FRT BUMPER ,FRT RH FENDER ,FRT RH DOOR ,REPAIR RR RHS DOOR AND RENEW DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF PANEL ASSY-FRONT DOOR ,RH,PANEL ASSY -FENDER ,RH.		\$3,840.00	\$1,920.00
	SPRAY FRT BUMPER ,FRT RHS FENDER ,FRT RHS DOOR ,RR RHS DOOR		\$2,400.00	\$2,200.00
	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM		\$280.00	\$280.00
	CHECK WIRING AND ELECTRICAL		\$100.00	\$100.00
	REMOVE AND REFIT SENSOR		\$100.00	\$80.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE AND REFIT /TRANSFER FRT RHS DOOR TRIM AND MECHANISM		\$160.00	\$160.00
	RENEW FRT RHS RIM		\$120.00	\$100.00
	ANTI RUST PROOFING		\$150.00	\$100.00
			\$7,530.00	\$5,320.00
GRAND TOTAL			\$13,131.00	\$8,138.00
	RECOMMENDED COST OF REPAIRS			\$8,138.00
Report Ref No: CD/FCI24070485/Rma3q2				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J




PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J



PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J



PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J



PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J



PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J



PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J



PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J



PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J



PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J



PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J



PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J



PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J



PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J



PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J



PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 17 of 17)

PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 3)

PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J



PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J



PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SNK 5491J

