

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24060008/AMA3Q2
Date: 06/12/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MFL0003414_04
Claimant Vehicle No : SLV2923R Insured Vehicle No : SNG8905J
Date of Loss: 08/06/2024 Nature of Claim: TP Claim No: MFL2024D0006827

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLV2923R
Make & Model: RENAULT GRAND SCENIC IV, 1.5 DCI EU6 (A) Engine No: K9KF649D016458
Reg. Date: 27/12/2017 (Man. Year: 2017) Chassis No: VF1RFA00258596330
Colour: Bronze Odometer: 118370 km
Engine Capacity: 1461 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R20 Rear Tyre Size: 195/55 R20
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,946.70	7,158.80	7,787.90	52.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,630.00	1,140.00	1,490.00	56.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,576.70	8,298.80	9,277.90	52.79
Approved Total (Overridden) (S\$)		6,600.00		
(S\$)	17,576.70	6,600.00	10,976.70	62.45
+ GST 9.00/9.00% (S\$)	1,581.90	594.00	987.90	62.45
Nett Amount (S\$)	19,158.60	7,194.00	11,964.60	62.45
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		7,621.25		
Global Sum Settlement (S\$)		7,600.00		

INSPECTION

Date of Assignment: 10/06/2024
Date Inspected: 10/06/2024 Inspected At: Twincar Automotive Pte Ltd - Kaki Bukit (HQ)
2 KAKI BUKIT AVENUE 2, #01-17 KAKI BUKIT
AUTOHUB
Singapore 417921
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2024)
Parts:	M1-MPV	RENAULT GRAND SCENIC IV 1.5 DCI EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV2923R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	1,512.00 FL	*1,512.00 FL
2	1		*REAR BUMPER CENTER BRACKET	Cracked	417.00 FL	*417.00 FL
3	2		*REAR BUMPER LOWER BRACKET	Cracked	180.00 FL	*180.00 FL
4	1		*REAR BUMPER LOWER DIFFUSER	Deformed	391.00 FL	*391.00 FL
5	1		*REAR BUMPER LOWER LID	Deformed	677.00 FL	*677.00 FL
6	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	634.00 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Not Necessary	680.00 FL	*- FL
8	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	1,064.00 FL	*532.00 FL
9	4		*REAR BUMPER REVERSE SENSOR O RING	Necessary (2 PCS ONLY)	80.00 FL	*40.00 FL
10	4		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	352.00 FL	*100.00 FL
11	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	450.00 FL	*- FL
12	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	234.00 FL	*- FL
13	1		*REAR END PANEL	Not Necessary	1,200.00 FL	*- FL
14	1		*REAR END PANEL INNER TOP GARNISH	Not Necessary	300.00 FL	*- FL
15	1		*REAR EXHAUST GASKET	Not Necessary	110.00 FL	*- FL
16	1		*REAR EXHAUST HEAT SHIELD COVER	Crumpled	306.00 FL	*306.00 FL
17	2		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	194.00 FL	*- FL
18	1		*REAR EXHAUST SILENCER BOX	Not Necessary	1,406.00 FL	*- FL
19	1		*REAR LH FENDER INNER SHIELD COVER	Not Necessary	276.00 FL	*- FL
20	1		*REAR TAILGATE	Cracked	2,327.00 FL	*2,327.00 FL
21	1		*REAR TAILGATE LOGO EMBLEM	Necessary	237.00 FL	*135.00 FL
22	1		*REAR TAILGATE RENAULT EMBLEM	Necessary	216.00 FL	*120.00 FL
23	1		*REAR TAILGATE SCENIC EMBLEM	Necessary	210.00 FL	*115.00 FL
24	2		*REAR TAILGATE HINGES L/R	Not Necessary	300.00 FL	*- FL
25	2		*REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	Not Necessary	120.00 FL	*- FL
26	1		*REAR TAILGATE MECHANISM LOCK	Not Necessary	312.00 FL	*- FL
27	1		*REAR TAILGATE OUTER COVER	Deformed	1,478.00 FL	*980.00 FL
28	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	300.00 FL	*- FL
29	2		*REAR TAILLAMP LOWER BRACKET L/R	Not Necessary	300.00 FL	*- FL
30	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
31	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
32	1		*SET REAR LH FENDER INNER SHIELD COVER CLIPS	Not Necessary	30.00 FS	*- FS
33	1		*REAR TAILGATE WINDSCREEN SEAL	Necessary	80.00 FS	*40.00 FS
34	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,573.00	7,942.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,626.30	783.20
Total Parts (S\$)	14,946.70	7,158.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	50.00
2	TO REMOVE ,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	80.00	30.00
4	TO RESPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	400.00
5	TO REMOVE AND CHARGE EXHAUST SILENCER BOX WITH PIPE RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	120.00	80.00
6	TO PROVIDE LABOUR WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND REALIGNBODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	400.00
7	TO APPLY ANTI RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	0.00
8	TO REMOVE AND REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	60.00
Gross Labour Cost (\$\$)			2,630.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >