



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SFH 4866D

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	DEFORMED	\$961.00	\$838.00
2	REAR BUMPER SIDE SKIRT @\$396.30	N/S NOT NECESSARY / O/S CRACKED	\$792.60	\$212.00
2	REAR BUMPER CENTER CLIP @\$46.80	NECESSARY	\$93.60	\$93.60
2	REAR BUMPER REFLECTOR @\$53.60	N/S NOT NECESSARY / O/S CRACKED	\$107.20	\$53.60
2	REAR BUMPER SIDE RETAINER @\$47.70	N/S NOT NECESSARY / O/S DEFORMED	\$95.40	\$47.70
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	\$279.80	\$0.00
2	REAR FENDER INNER COWLING	NOT NECESSARY	\$193.20	\$0.00
1	REAR FENDER AIR VENT RH	NOT NECESSARY	\$106.20	\$0.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$515.70	\$0.00
	LESS 20.00% DISCOUNT		(\$628.94)	(\$248.98)
			\$2,515.76	\$995.92

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIP (SN)	NECESSARY	\$80.00	\$30.00
1	SET REAR FENDER INNER TRIM CLIP (SN)	NOT NECESSARY	\$50.00	\$0.00
1	SET REAR FENDER INNER COWLING CLIP (SN)	NOT NECESSARY	\$50.00	\$0.00
1	SET REAR END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	\$30.00	\$0.00
1	REAR END PANEL INSULATION SEAL (SN)	NOT NECESSARY	\$150.00	\$0.00
1	REVERSE SENSOR (SN)	TORN	\$220.00	\$200.00
			\$580.00	\$230.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL		\$1,600.00	\$300.00
	TO SPRAY PAINT AFFECTED AREA		\$1,200.00	\$300.00
	TUFF COAT	NOT NECESSARY	\$250.00	\$0.00
	WIRING CHECK		\$120.00	\$30.00
	CONDUCT WATER LEAKAGE TEST	NOT NECESSARY	\$180.00	\$0.00
	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	NOT NECESSARY	\$250.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	NOT NECESSARY	\$80.00	\$30.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC		\$280.00	\$0.00
			\$3,960.00	\$660.00
GRAND TOTAL			\$7,055.76	\$1,885.92
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$1,500.00
Report Ref No: CS/INC24060080/Tqh3m4				

TOTAL FOR SPARE PARTS: \$ 3,095.76 \$ 1,225.92
TOTAL FOR LABOUR : \$ 3,960.00 \$ 660.00
TOTAL REPAIR COST: \$ 7,055.76 \$ 1,885.92

MTH

MOHAMAD TAUFIKH

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.