

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 10.06.2024

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SFH4866D**
MODEL : **MAZDA 5**
DATE OF ACCIDENT : 01.06.2024
TIME OF ACCIDENT : 13:45 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER	1	\$ 961.00	\$ 961.00
2	REAR BUMPER SIDE SKIRT	2	\$ 396.30	\$ LHX ^{nm} 792.60
3	REAR BUMPER CENTER CLIP	2	\$ 46.80	\$ 93.60
4	REAR BUMPER REFLECTOR	2	\$ 53.60	\$ LHX ^{nm} 107.20
5	REAR BUMPER SIDE RETAINER	2	\$ 47.70	\$ LHX ^{nm} 95.40
6	REAR BUMPER REINFORCEMENT	1	\$ 279.80	\$ 279.80
7	REAR FENDER INNER COWLING	2	\$ 96.60	\$ 193.20
8	REAR FENDER AIR VENT RH	1	\$ 106.20	\$ 106.20
9	REAR END PANEL	1	\$ 515.70	\$ 515.70

TOTAL PRICE \$ 3,144.70
LESS 20% \$ 628.94
SUB TOTAL PRICE \$ 2,515.76

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET)	1	\$ 80.00	\$ 80.00
2	REAR FENDER INNER TRIM CLIP (SET)	1	\$ 50.00	\$ 50.00
3	REAR FENDER INNER COWLING CLIP (SET)	1	\$ 50.00	\$ 50.00
4	REAR END PANEL TOP GARNISH CLIP (SET)	1	\$ 30.00	\$ 30.00
5	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00
6	REVERSE SENSOR	1	\$ 220.00	\$ 220.00

TOTAL \$ 580.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SFH4866D**
 MODEL : **MAZDA 5**
 DATE OF ACCIDENT : **01.06.2024**
 TIME OF ACCIDENT : **13:45 HOURS**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	300
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	300
3	TUFF COAT	\$ 250.00	x nm
4	WIRING CHECK	\$ 120.00	30
5	CONDUCT WATER LEAKAGE TEST	\$ 180.00	x nm
6	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	x nm
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	30
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00	x nm

660

TOTAL \$ 3,960.00

945.92

230

660

1885.92

1/5\$1500

03days

X

ESTIMATE REPORT

TOTAL PARTS COST : \$ 3,095.76
 TOTAL LABOUR COST : \$ 3,960.00
 TOTAL REPAIR COST : \$ 7,055.76

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfui 97495729

wp' 13/6/24 @ 12pm

4/5 Resy after repair

Tanfui c lkkauto in

for 03days