



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Report Reference : **TP / 24001-04/MY / 2024**
Date of Report : **8 Apr 2024**

LA Rentals Pte Ltd
C/o 48 Toh Guan Road
#02-103/104 Enterprise Hub
Singapore 608586

THIRD PARTY SURVEY
ACCIDENT HAPPENED ON 28 Mar 2024

Workshop Address : Lay Auto Garage Pte Ltd
No.48 Toh Guan Road
#02-103/104 Enterprise Hub
Singapore 608586

As per your instruction dated **2 Apr 2024** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SMJ 4713 T**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No	: SMJ 4713 T	Engine No	: LEB7105966
Model	: Honda Shuttle	Mileage	: 135909
Year / Capacity	: 2019/1496	Colour	: Silver
Chassis No	: GP72004606		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	: 195/65 R15	Triangle	5.00	mm	Normal
REAR O/S	: 195/65 R15	Triangle	5.00	mm	Normal
FRONT N/S	: 195/65 R15	Triangle	5.00	mm	Normal
REAR N/S	: 195/65 R15	Triangle	5.00	mm	Normal



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 6 working days to complete.
5. Enclosed number of photograph : 62 copies.
6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SMJ 4713 T**
 Report No: **TP/ 24001-04/MY / 2024**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Rear windscreen moulding	Necessary	\$ 95.60	\$ 95.60 /
1	Rear tailgate	Damage	\$ 1219.00	\$ 1219.00 1193 /
2	Rear tailgate dampers	Intact	\$ 330.00	\$
1	Rear tailgate inner board	Intact	\$ 320.00	\$
1	Rear tailgate lock	Damage	\$ 226.50	\$ 226.50 /
1	Rear tailgate rubber	Damage	\$ 168.50	\$ 168.50 /
1	Rear tailgate 'SHUTTLE' emblem	Necessary	\$ 69.00	\$ 69.00 /
1	Rear tailgate 'HYBRID' emblem	Necessary	\$ 45.00	\$ 45.00 /
1	Rear end panel	Damage	\$ 560.80	\$ 560.80 x R
1	Rear end panel inner garnish	Damage	\$ 155.50	\$ 155.50 x nn
1	Rear bumper	Damage	\$ 1072.50	\$ 1072.50 985 /
2	Rear bumper reflectors	Intact	\$ 148.20	\$
2	Rear bumper side retainers	Necessary	\$ 75.00	\$ 75.00 /
			\$ 4485.60	\$ 3687.40
	Discount	20.0%	\$ 897.12	\$ 737.48
			\$ 3588.48	\$ 2949.92
<u>Special Nett Items</u>				
1	Rear windscreen sealant	Necessary	\$ 100.00	\$ 60.00 50
1	Rear bumper clip (1 set)	Necessary	\$ 39.00	\$ 39.00 30
1	Rear reverse sensor (1 set)	Damage	\$ 320.00	\$ 280.00 200
			\$ 459.00	\$ 379.00

Spare Parts Total \$ 4047.48 \$ 3328.92

Vehicle No: **SMJ 4713 T**
 Report No: **TP/ 24001-04/MY / 2024**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 4047.48	\$ 3328.92
1	To disconnect and reconnect, check electrical wiring, harness wires, sockets, replace damaged parts.	\$ 50.00	\$ 40.00 30
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 160.00	\$ 80.00 50
3	To remove and refit rear bumper sensor.	\$ 150.00	\$ 80.00 30
4	To remove and refit rear windscreen glass.	\$ 180.00	\$ 150.00 120
5	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1100.00	\$ 750.00 600
6	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1100.00	\$ 750.00 600
7	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 100.00	\$ 60.00 30
Total		<u>\$ 6887.48</u>	<u>\$ 5238.92</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ **4200.00**

SDLS: FOUR THOUSAND TWO HUNDRED ONLY

5 days


 Qualified Appraiser