

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24070492/UNP3E2**Date:** 02/01/2025REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : FBD252U **Insured Vehicle No :** YQ6067H

Date of Loss: 20/07/2024 Nature of Claim: TP Claim No: DMCV2400149H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBD252U**

Make & Model: YAMAHA MTN850A, 847cc Engine No: N701E127816

Reg. Date: 28/08/2018 (Man. Year: 2018) Chassis No: JYARN43T000003917

Colour: Silver Odometer: 53156 km

Engine Capacity: 847 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70Z R17 Rear Tyre Size: 180/55Z R17

Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,751.00	2,666.70	10,084.30	79.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	400.00	450.00	52.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,601.00	3,066.70	10,534.30	77.45
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	13,601.00	2,450.00	11,151.00	81.99
+ GST 9.00/9.00% (S\$)	1,224.09	220.50	1,003.59	81.99
Nett Amount (S\$)	14,825.09	2,670.50	12,154.59	81.99

INSPECTION

Date of Assignment: 30/07/2024

Date Inspected: 31/07/2024 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)
BLK 8 Defu South Street 1, #04-28 JTC Defu Industrial City
Singapore 533758

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Jan 2025)	
Parts:	N/A	YAMAHA MTN850A 847cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBD252U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BALANCER HANDLE	N/S Cut / O/S Not Necessary	54.00 F	*27.00 FL
2	1		*BAR HANDLE	Bent	223.00 F	*223.00 FL
3	2		*BEARING	Not Necessary	34.00 F	*- FL
4	1		*BRACKET FOOTREST REAR LH (CUT)	Not Consistent With The Impact	91.00 F	*- FL
5	1		*COOLANT (BMW)	Necessary	47.00 F	*47.00 FL
6	1		*COVER ASSY	Not Necessary	73.00 F	*- FL
7	1		*COVER CRANKCASE 1 (CUT)	Not Consistent With The Impact	209.00 F	*- FL
8	1		*COVER SIDE RADIATOR LH	Cut	90.00 F	*90.00 FL
9	1		*COVER SIDE RADIATOR RH (CUT)	Not Consistent With The Impact	90.00 F	*- FL
10	1		*DAMPER	Not Necessary	5.00 F	*- FL
11	1		*EMBLEM	Not Necessary	22.00 F	*- FL
12	1		*EMBLEM, YAMAHA	Not Necessary	11.00 F	*- FL
13	1		*FOOTREST REAR 1	Serviceable	30.00 F	*- FL
14	1		*FULL SYSTEM (LEOVINCE) LV ONE EVO (CUT)	Not Consistent With The Impact	5,972.00 F	*- FL
15	1		*GASKET	Not Necessary	8.00 F	*- FL
16	1		*GASKET COVER MAGNET	Not Necessary	23.00 F	*- FL
17	1		*LAMP SIGNAL FRONT LH	Cracked	38.00 F	*38.00 FL
18	1		*LAMP SIGNAL FRONT RH (CUT)	Not Consistent With The Impact	38.00 F	*- FL
19	1		*LEVER BRAKE (CUT)	Not Consistent With The Impact	1,240.00 F	*- FL
20	1		*LEVER CLUTCH	Cut	1,240.00 F	*765.00 FL
21	1		*MID PIN COTTER	Not Necessary	6.00 F	*- FL
22	1		*MIRROR LH	Cut	71.00 F	*71.00 FL
23	1		*MIRROR RH (CUT)	Not Consistent With The Impact	71.00 F	*- FL
24	1		*MT09 ENGINE SLIDER	Cut	775.00 F	*775.00 FL
25	1		*MUDGUARD FRONT	Repair	249.00 F	*- FL
26	1		*O-RING	Not Necessary	5.00 F	*- FL
27	1		*O-RING	Not Necessary	10.00 F	*- FL
28	1		*O-RING	Not Necessary	7.00 F	*- FL
29	1		*O-RING (WATER PUMP)	Not Necessary	8.00 F	*- FL
30	1		*O-RING WATER PIPE	Not Necessary	8.00 F	*- FL
31	1		*RADIATOR COMP	Dented / Bent	492.00 F	*492.00 FL
32	1		*RIM FRONT ASSY	Repair	889.00 F	*- FL
33	1		*SCOOP, AIR 2	Not Necessary	112.00 F	*- FL
34	1		*SEAL	Not Necessary	8.00 F	*- FL
35	2		*SEAL OIL (25X40X5)	Not Necessary	26.00 F	*- FL
36	1		*SLIDER WHEEL FRONT (EVOTECH)	Cut	148.00 F	*148.00 FL
37	1		*VALVE TYRE 11.3MM BLACK (RACING VALVE)	Not Necessary	41.00 F	*- FL
38	1		*SLIDER ENGINE (EVOTECH)	Cut	287.00 F	*287.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) **12,751.00** **2,963.00**
- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 296.30

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)						12,751.00 2,666.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	850.00	400.00
Gross Labour Cost (S\$)			850.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >