

CHIN CHUAN GARAGE

Blk 3006 Ubi Rd 1, #01-336 Singapore 408700

H/P: 96736356 (Jack) Fax: 6747 8378

Reg. No.: 50600700J

TP Cyberly,
Xiao Chen.

Name: Chia Chee Kiong (Xie ZhiQiang)

Address: c/o Blk 3006 Ubi Rd 1

#01-336 Singapore 408700

Date: 24-Jul-24

Vehicle No.: SGU 5986 D

Model: Subaru Forester

Items:

S/N	Description	Amount	
1 pc	Front bumper <i>Rehnd</i>	\$ 692.00	nett ✓
2 pcs	Bumper side retainer (\$39.50 x 2) <i>HH could not</i>	\$ 79.00	nett <i>39.50</i>
1 pc	Front bumper grille <i>lot</i>	\$ 382.50	nett ✓
1 pc	Front bumper grille chrome <i>cut</i>	\$ 205.00	nett ✓
1 pc	Front bumper washer cover LHS <i>from not a</i>	\$ 88.50	nett +
1 pc	Front bumper washer mount LHS <i>could</i>	\$ 155.00	nett ✓
1 pc	Front bumper <i>Top</i> garnish <i>new</i>	\$ 185.00	nett +
1 pc	Front bumper side garnish upper LHS <i>missing</i>	\$ 56.50	nett ✓
1 pc	Front bumper side garnish lower LHS <i>new</i>	\$ 36.50	nett +
1 pc	Front bumper fog lamp LHS <i>could</i>	\$ 335.60	nett ✓
1 pc	Front bumper fog lamp cover LHS <i>lot</i>	\$ 98.00	nett ✓
1 pc	Front bumper inner garnish LHS <i>new</i>	\$ 195.00	nett +
1 pc	Front reinforcement <i>Rehnd</i>	\$ 361.20	nett ✓
2 pcs	Front bumper inner sponge <i>new</i>	\$ 186.20	nett +
1 pc	Front headlamp LHS <i>lot</i>	\$ 2,550.00	nett ✓
1 pc	Front headlamp lower bracket LHS <i>could</i>	\$ 89.50	nett ✓
1 pc	Front number plate housing <i>new</i>	\$ 68.50	nett +
1 pc	Front bonnet centre grille <i>new</i>	\$ 245.20	nett +
1 pc	Front bonnet centre grille chrome <i>new</i>	\$ 223.00	nett +
1 pc	Front fender inner garnish LHS <i>new torn</i>	\$ 195.50	nett ✓
1 pc	Front fender LHS <i>Repair</i>		+
		20% repair	
		\$ 6,047.70	
		Less 10%	\$ 604.77
		Total	\$ 5,442.93

5120.80

Less 20% : 4096.64

CHIN CHUAN GARAGE

Blk 3006 Ubi Rd 1, #01-336 Singapore 408700

H/P: 96736356 (Jack) Fax: 6747 8378

Reg. No.: 50600700J

Special Nett Items:

1 set	Front Bumper clips	75	\$	50.00	30
1 set	Front bumper garnish clips	75	\$	50.00	+
1 set	Front fender inner garnish clips	75	\$	50.00	+
1 set	Front number plate with housing	75	\$	45.00	✓
				<u>\$</u>	<u>195.00</u>

Labour

1)	To check wiring, lighting and resetting head lamps focusing	\$	50.00	30
	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damage consistent to the accident. (including all repair parts)	\$	700.00	400
3)	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$	800.00	400
4)		<u>\$</u>	<u>1,550.00</u>	

830

Adrian G
2/3. 31/07/28

042p

total: 5001.64
1/3. AK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: