

ASS. REC. BY:

REF:

C72/

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 13.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 58084 Yr Regn: 03, 23

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Pro c.c. 1798Colour M.P. White / Red A/C: Insured / Std / NI / NASp. Reading 93761 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU10.3096704Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Portun

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 2/7/24 D.O.I. 30/7/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/8 @ 1284.88 Carbur

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation

S - RS. SI

Fuel

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Not Authoited
Primary B4 paint
81284.88

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5868U

AAD2407-013

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

30 JUL 2024

SHC5868U

JTDKB3FU103096704

200303878K

TOYOTA

PRIUS GEN 4

2/7/2024

SNC9024R/CHINA

31/3/2023

PART

- 1 UNIT ASSY, HEADLAMP, LH
- 1 FENDER SUB-ASSY, FRONT LH
- 1 LINER, FRONT FENDER, LH
- 1 EMBLEM, SIDE PANEL
- 1 COVER, FRONT BUMPER
- 1 SUPPORT SUB-ASSY, RADIATOR, LH
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 COVER, FRONT BUMPER HOLE, LH
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 SUPPORT, FRONT BUMPER SIDE, LH
- 1 STAY SUB-ASSY, FRONT BUMPER, LH
- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 MOULDING, FRONT BUMPER SIDE, LH

LIST

\$	Sm	3,325.56	X
\$	R	1,236.69	X
\$	Sm	265.55	X
\$	M	68.88	—
\$	Bu/M	659.40	—
\$	Sm	308.91	X
\$	Sm	100.91	X
\$	R	902.16	1
\$	Sm	38.22	✓
\$	Sm	532.88	X
\$	Sm	224.70	X
\$	Sm	100.49	X
\$	Sm	59.85	X
\$	Sm	74.97	X
\$	Sm	120.86	X
TOTAL	\$	8,020.03	
25%	\$	2,005.01	
	\$	6,015.02	

Special Nett

- 1SET BUMPER CLIP FRT
- 1SET FRNT BUMPER RETAINER CLIP
- 1SET FENDER CLIP
- 1 FENDER LINER CLIP

\$	M	65.00	60sm
\$	M	85.00	X
\$	M	130.00	X
\$	M	65.00	X

Trans-cab Auto Services Pte Ltd

AAD2407-013

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5868U

TOTAL \$ **345.00****TOTAL PARTS** \$ **2,300.00****LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i> 240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	<i>200</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>nn</i> 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	<i>440</i>
To reinstall rear bumper parking sensor.	\$	<i>nn</i> 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>100</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X

TOTAL \$ **5,100.00****Over All Total** \$ **13,415.02**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

2 days

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5868U

AAD2407-013

(PART-BY-PART) Repair Days

~~06~~ Days

2 days