

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. : SAC2401058

INV Date : 18-10-2024

Reference CD/CTI24070497/Kua3q2

Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 5868U
Insured Veh. SNC 9024R
Claim No. SNM24D203827
Policy No. DMHCSNA00027592301
Accident Date 02/07/2024
Inspection Date 30/07/2024

Description	Amount
Survey Inspection	280.00
Resurvey Inspection	0.00
Digital Photographs	0.00
Transportation	0.00
Sub-Total	280.00
GST (9%)	25.20
Grand Total	305.20

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS CHINA TAIPING INSURANCE (S) PTE LTD	Ref:	CD/CTI24070497/Kua3q2
3 ANSON ROAD #16-00	Date:	18/10/2024
SPRINGLEAF TOWER SINGAPORE 079909	Code:	CTI

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SNC 9024R	Veh. Inspected	SHC 5868U
Policy No.	DMHCSNA00027592301	Coverage	0
Claim No.	SNM24D203827	Excess	\$0.00
Assign From	JACQUELINE TAN	Assign Date	31/07/2024

2. Vehicle Details

Make & Model	TOYOTA PRIUS 5DR HATCHBACK (AUTO)(2WD)	C.C	1798
Engine No.	2ZR2R37846	Year of Reg.	31/03/2023
Chassis No.	JTDKB3FU103096704	Colour	METALLIC PEARL WHITE/RED
Odometer	93761 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	SAILUN	9
L/H Front Tyre	195/65R15	SAILUN	9
R/H Rear Tyre	195/65R15	SAILUN	9
L/H Rear Tyre	195/65R15	SAILUN	9

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/07/2024	Inspection Date	30/07/2024
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SHC 5868U

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	UNIT ASSY ,HEADLAMP LH	SERVICEABLE	\$3,325.56	\$0.00
1	FENDER SUB-ASSY ,FRONT LH	TO REPAIR SEE LABOUR	\$1,236.69	\$0.00
1	LINER ,FRONT FENDER LH	SERVICEABLE	\$265.55	\$0.00
1	EMBLEM SIDE PANEL	NECESSARY	\$68.88	\$68.88
1	COVER FRONT BUMPER	BUCKLED /DENTED	\$659.40	\$659.40
1	SUPPORT SUB ASSY RADIATOR LH	SERVICEABLE	\$308.91	\$0.00
1	ABSORBER FRONT BUMPER ENERGY	SERVICEABLE	\$100.91	\$0.00
1	REINFORCEMENT SUB-ASSY ,FRONT BUMPER	TO REPAIR SEE LABOUR	\$902.16	\$0.00
1	COVER FRONT BUMPER HOLE ,LH	CUT	\$38.22	\$38.22
1	GRILLE SUB-ASSY ,RADIATOR	SERVICEABLE	\$532.88	\$0.00
1	GRILLE RADIATOR LOWER NO.1	SERVICEABLE	\$224.70	\$0.00
1	SUPPORT FRONT BUMPER SIDE ,LH	SERVICEABLE	\$100.49	\$0.00
1	STAY SUB-ASSY ,FRONT BUMPER LH	SERVICEABLE	\$59.85	\$0.00
1	BRACKET ,FRONT BUMPER SIDE LH	SERVICEABLE	\$74.97	\$0.00
1	MOULDING FRONT BUMPER SIDE LH	SERVICEABLE	\$120.86	\$0.00
LESS 25.00% DISCOUNT			(\$2,005.01)	(\$191.62)
			\$6,015.02	\$574.88
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET BUMPER CLIP FRT (SN)	NECESSARY	\$65.00	\$60.00
1	SET FRT BUMPER RETAINER CLIP (SN)	NOT NECESSARY	\$85.00	\$0.00
1	SET FENDER CLIP (SN)	NOT NECESSARY	\$130.00	\$0.00
1	FENDER LINER CLIP (SN)	NOT NECESSARY	\$65.00	\$0.00
			\$345.00	\$60.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	NOT NECESSARY	\$240.00	\$0.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	NOT NECESSARY	\$380.00	\$0.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FENDER SUB-ASSY FRONT LH AND REINFORCEMENT SUB-ASSY ,FRONT BUMPER.		\$1,600.00	\$200.00
	TO TRANSFER OF REAR END PANEL FITTINGS ATTACHMENT TO FACILITATE BODYWORK REPAIR	NOT NECESSARY	\$380.00	\$0.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION		\$1,600.00	\$440.00
	TO REINSTALL REAR BUMPER PARKING SENSOR	NOT NECESSARY	\$170.00	\$0.00
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	NOT NECESSARY	\$170.00	\$0.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED		\$170.00	\$10.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	NOT NECESSARY	\$220.00	\$0.00
	TO REMOVE AND REFIT OF REAR FENDER FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	NOT NECESSARY	\$170.00	\$0.00
			\$5,100.00	\$650.00
GRAND TOTAL			\$11,460.02	\$1,284.88
RECOMMENDED COST OF REPAIRS				\$1,284.88
Report Ref No: CD/CTI24070497/Kua3q2				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SHC 5868U



PHOTOGRAPHS FOR VEHICLE NO. : SHC 5868U



PHOTOGRAPHS FOR VEHICLE NO. : SHC 5868U



PHOTOGRAPHS FOR VEHICLE NO. : SHC 5868U



PHOTOGRAPHS FOR VEHICLE NO. : SHC 5868U

