

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070500/AMA3Q2**Date:** 13/10/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7230039032
Claimant Vehicle No : SMV3613S **Insured Vehicle No :** SLX8507J
 Date of Loss: 25/07/2024 Nature of Claim: TP Claim No: 5715881667SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMV3613S**
 Make & Model: HONDA CIVIC, 1.6 VTI CVT (A) Engine No: R16B25520251
 Reg. Date: 27/08/2020 (Man. Year: 2020) Chassis No: MRHFC5650LT000157
 Colour: White Odometer: 73885 km
 Engine Capacity: 1597 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Tourador 6 mm Rear Left Side: Tourador 6 mm
 Front Right Side: Tourador 6 mm Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,101.00	4,440.00	10,661.00	70.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,820.00	1,800.00	2,020.00	52.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,921.00	6,240.00	12,681.00	67.02
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	18,921.00	5,000.00	13,921.00	73.57
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		5,827.25		
Global Sum Settlement (S\$)		5,800.00		

INSPECTION

Date of Assignment: 29/07/2024
 Date Inspected: 29/07/2024 Inspected At: Genus Performance (HQ)
 CLOSE, #03-03 MEGA @ WOODLANDS
 Singapore 737856
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,150.00 F	*655.00 FL
2	1		*REAR BOOT LID EMBLE LOGO	Necessary	120.00 F	*55.00 FL
3	1		*SET REAR BOOT LID EMBLE LOGO CLIPS	Not Necessary	80.00 F	*- FL
4	1		*REAR BOOT LID CIVIC LOGO	Necessary	80.00 F	*45.00 FL
5	1		*REAR BOOT LID RH LOGO	Not Necessary	85.00 F	*- FL
6	1		*REAR BOOT LID VTEC LOGO	Necessary	40.00 F	*40.00 FL
7	2		*REAR BOOT LID SIDE REFLECTOR	Cut	710.00 F	*558.00 FL
8	1		*REAR BOOT LID INNER RUBBER	Cut	285.00 F	*285.00 FL
9	1		*REAR BOOT LID NUMBER PLATE	Dented	100.00 F	*50.00 FL
10	1		*SET REAR BOOT LID INNER TRIM BOARD CLIPS	Necessary	80.00 F	*30.00 FL
11	2		*REAR TAIL LAMP	Cracked	1,042.00 F	*661.00 FL
12	2		*REAR TAIL LAMP PANEL	Repair	422.00 F	*- FL
13	4		*REAR TAIL LAMP CLIPS	Not Necessary	13.00 F	*- FL
14	2		*REAR FENDER INNER TRIM	Not Necessary	1,050.00 F	*- FL
15	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	80.00 F	*- FL
16	1		*REAR BUMPER	Distorted	950.00 F	*667.00 FL
17	2		*REAR BUMPER SIDE BRACKET	Not Necessary	370.00 F	*- FL
18	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 F	*200.00 FL
19	1		*SET REAR BUMPER CLIPS	Necessary	60.00 F	*30.00 FL
20	1		*REAR BUMPER CENTER LOWER COVER	Not Necessary	385.00 F	*- FL
21	1		*REAR BUMPER REINFORCEMENT	Dented	688.00 F	*361.00 FL
22	1		*REAR BUMPER LOWER GARNISH	Deformed	285.00 F	*285.00 FL
23	1		*REAR BUMPER INNER GARNISH	Not Necessary	415.00 F	*- FL
24	2		*REAR BUMPER MUD SHIELD	Not Necessary	230.00 F	*- FL
25	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	210.00 F	*- FL
26	2		*REAR BUMPER SIDE REFLECTOR CHROME	Not Necessary	370.00 F	*- FL
27	1		*REAR EXHAUST CHROME PIPE	Not Necessary	220.00 F	*- FL
28	1		*END PANEL	Distorted	825.00 F	*548.00 FL
29	1		*END PANEL TOP GARNISH	Deformed	288.00 F	*288.00 FL
30	1		*REAR SPARE TYRE TOP COVER	Not Necessary	688.00 F	*- FL
31	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	788.00 F	*- FL
32	1		*REAR FLOOR PANEL	Repair	1,850.00 F	*- FL
33	1		*REAR BOOT LID OUTER GARNISH	Cracked	265.00 F	*265.00 FL
34	1		*REAR BUMPER LOWER CHROME GARNISH	Cracked	110.00 F	*110.00 FL
35	1		*REAR BOOTLID INNER TRIM BOARD	Deformed	232.00 F	*232.00 FL
36	1		*REAR BOOTLID LOCK	Damaged	185.00 F	*185.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	15,101.00	5,550.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	1,110.00
Total Parts (\$)	15,101.00	4,440.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX REAR WINDSCREEN	New	150.00	0.00
2	GUM	New	50.00	0.00
3	TO REMOVE & REFIX REAR CUSHION	New	120.00	60.00
4	TO REMOVE & REFIX REVERSE SENSOR	New	100.00	50.00
5	TO CHECK WIRING	New	80.00	30.00
6	TUFF KOTE	New	120.00	60.00
7	PANEL BEATING	New	1,600.00	800.00
8	SPRAY PAINTING	New	1,600.00	800.00
Gross Labour Cost (\$\$)			3,820.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >