

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070502/AUA3Q2**Date:** 17/06/2025REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220078291
Claimant Vehicle No :	SMQ4216A	Insured Vehicle No :	SN86D
Date of Loss:	25/07/2024	Nature of Claim:	TP
		Claim No:	4754959628SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ4216A	Engine No:	L15B5672224
Make & Model:	HONDA HR-V, 1.5 LX CVT (A)	Chassis No:	JHMRU1830JX202221
Reg. Date:	15/11/2019 (Man. Year: 2019)	Odometer:	131716 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,908.72	9,368.96	4,539.76	32.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,260.00	3,080.00	2,180.00	41.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,168.72	12,448.96	6,719.76	35.06
Approved Total (Overridden) (S\$)		9,600.00		
(S\$)	19,168.72	9,600.00	9,568.72	49.92
+ GST 9.00/9.00% (S\$)	1,725.18	864.00	861.18	49.92
Nett Amount (S\$)	20,893.90	10,464.00	10,429.90	49.92
+ Car Rental (16.0 x S\$100.00/day) (S\$)		1,600.00		
Nett Liability (S\$)		12,064.00		
Global Sum Settlement (S\$)		12,050.00		

INSPECTION

Date of Assignment:	26/07/2024		
Date Inspected:	26/07/2024	Inspected At:	J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578 Singapore 539186
Estimated Period of Repair:	12.0 days		

Adjuster: ADRIAN LING**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*HEADLAMP	Cracked	3,711.80 FL	*3,711.80 FL
2	2		*HEADLAMP CHROME	Not Necessary	156.60 FL	*- FL
3	1		*FRT BUMPER	Deformed	830.00 FL	*540.00 FL
4	2		*FRT BUMPER RETAINER	Not Necessary	124.80 FL	*- FL
5	2		*FRT BUMPER HOLDER	Not Necessary	69.00 FL	*- FL
6	2		*FRT BUMPER FOG LAMP	Not Necessary	640.00 FL	*- FL
7	2		*FRT BUMPER FOG LAMP COVERS	Not Necessary	72.00 FL	*- FL
8	1		*FRT BUMPER CENTRE GRILLE	Not Necessary	90.00 FL	*- FL
9	12		*FRT BUMPER CLIPS	Necessary	46.80 FL	*46.80 FL
10	1		*FRT BUMPER REINFORCEMENT	Deformed	430.00 FL	*345.00 FL
11	1		*FRT GRILLE	Cracked	297.00 FL	*297.00 FL
12	1		*FRT GRILLE BASE	Cracked	510.00 FL	*510.00 FL
13	1		*FRT GRILLE CHROME	Cracked	232.60 FL	*232.60 FL
14	1		*FRT GRILLE H EMBLEM	Necessary	36.40 FL	*36.40 FL
15	10		*FRT GRILLE CLIPS	Necessary	39.00 FL	*39.00 FL
16	1		*FRT GRILLE TOP GARNISH	Not Necessary	57.50 FL	*- FL
17	1		*FRT GRILLE BRACKET	Crumpled	62.10 FL	*62.10 FL
18	1		*TAILGATE	Distorted	934.40 FL	*934.40 FL
19	1		*H EMBLEM	Not Necessary	36.40 FL	*- FL
20	1		*I-VTEC EMBLEM	Necessary	26.40 FL	*26.40 FL
21	1		*HR-V EMBLEM	Necessary	26.10 FL	*26.10 FL
22	1		*TAILGATE REFLECTORS	N/S Cracked	589.20 FL	*298.00 FL
23	1		*TAILGATE LOCK	Damaged	178.20 FL	*178.20 FL
24	1		*TAILGATE W/STRIP	Not Necessary	107.70 FL	*- FL
25	1		*TAILGATE TRIMBOARD	Cracked	168.50 FL	*168.50 FL
26	1		*TAILGATE OUTER GARNISH W/CHROME	Not Necessary	281.30 FL	*- FL
27	1		*TAILGATE INNER HANDLE	Not Necessary	24.80 FL	*- FL
28	1		*LH TAILLAMP	Cracked	438.50 FL	*438.50 FL
29	1		*LH TAILLAMP CLIP	Not Necessary	5.90 FL	*- FL
30	1		*LH TAILLAMP INNER PANEL	Buckled	195.30 FL	*195.30 FL
31	1		*REAR BUMPER	Distorted	594.40 FL	*594.40 FL
32	2		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	819.20 FL	*409.60 FL
33	1		*REAR BUMPER RETAINER	N/S Damaged	33.00 FL	*16.50 FL
34	1		*REAR BUMPER SIDE LH	Distorted	136.50 FL	*136.50 FL
35	8		*REAR BUMPER CLIPS	Necessary	31.20 FL	*31.20 FL
36	1		*REAR LH FENDER	Buckled	790.90 FL	*790.90 FL
37	1		*REAR LH FENDER WHEEL ARCH GARNISH	Deformed	237.40 FL	*158.00 FL
38	1		*REAR LH FENDER INNER TRIM	Deformed	260.60 FL	*260.60 FL
39	5		*REAR LH FENDER INNER TRIM CLIPS	Necessary	19.50 FL	*19.50 FL
40	1		*REAR LH AIR DUCT	Deformed	37.50 FL	*37.50 FL
41	1		*REAR LH MUDFLAP	Not Necessary	140.30 FL	*- FL
42	1		*END PANEL	Dented	607.30 FL	*435.00 FL
43	1		*END PANEL INNER GARNISH	Deformed	166.60 FL	*166.60 FL
44	1		*SPARE TYE CARDBOARD	Torn	232.00 FL	*232.00 FL
45	1		*SPARE TYE PANEL	Not Necessary	837.50 FL	*- FL
46	1		*SPARE TYE PANEL LOWER COVER	Not Necessary	151.80 FL	*- FL
47	1		*REAR LH DOOR	Not Necessary	935.10 FL	*- FL
48	1		*TOOL BOX	Torn	236.80 FL	*236.80 FL
49	1		*CAMERA	Not Necessary	400.00 FS	*- FS
50	1		*FRT NO PLATE	Not Necessary	40.00 FS	*- FS
51	1		*REAR NO PLATE	Not Necessary	40.00 FS	*- FS
52	1		*REAR W/SCREEN GUM	Necessary	50.00 FS	*50.00 FS
53	1		*REAR W/SCREEN SEAL	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 17,245.90 11,691.20

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 20.00/20.00% (S\$)					3,337.18	2,322.24
Total Parts (S\$)					13,908.72	9,368.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	1,400.00
2	SPRAY PAINTING	New	2,500.00	1,200.00
3	WIRING FRT & REAR	New	60.00	60.00
4	RUST PROOFING	New	80.00	80.00
5	UPHOLSTERY	New	120.00	60.00
6	REMOVE & REFIT REAR W/SCREEN	New	120.00	120.00
7	TRANSFER TAILGATE PARTS	New	80.00	60.00
8	REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
9	REMOVE & REFIT CAMERA	New	150.00	50.00
Gross Labour Cost (\$\$)			5,260.00	3,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >